CS/UOI21001967/Aqd3

ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No:

Claims No: M11D12042102

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rport: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 6 days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: GBJ6111Y 1st Regn: 2019 June.

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: Peugeot Partner c.c 1499.

Colour: White A/C: Insured / Std / NI / NA

Sp.Reading: 50183 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: VR3EFYHZRKJ635027

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/60R16

R: 205/60R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front			Rear		
R/Bal	06	mm	R/Bal	06	mm
L/Bal	06	mm	L/Bal	06	mm

D.O.A. D.O.I. 10/02/21

Survey held at: Auto Bullak

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time	Action / Instruction
	TP 401
	LS $8300, 6 days (Red $16774.46, 67%)
	MV :
	PV :
	Nett :

525K

Date/Time File Pass to? : Preli. Report

29/03 Typist : Final Report

Date/Time File Return to?

Days Of Repair: 6

Resurvey No. of Trip: 2

15x25=375

Survey Fee:	375+250
Transportation:	60
B+PS	80+80
Photo	80
Other	
	925

Add Fee: Site Insp. Interview Tech. Insp.

588

OSP

13/4/21

Report Format: TP

Lump Sum / [redacted]: 8300