REPAIR ESTIMATE*

VEHICLE NO SHC3357R

MAKE :

MODEL : HYUNDAI IONIQ G2

DATE 08/02/21 12:00 AM

CHIANG /NTUC PIP

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
1	FRONT BUMPER COVER			$430.90	/CRK
1	FRONT BUMPER BRACKET LH			$35.00	/CRK
1	FRONT BUMPER CENTRE MOULDING			$368.50	?
1	HEAD LAMP ASSY LH			$1,993.65	/CRK
1	FRONT DAY LIGHT LH			$642.50	?
1	FRONTSIDE GRILLE LH			$186.90	/SCR
				$3,657.45	
	20.00%			$731.49	
	DISCOUNTED TOTAL			$2,925.96	
	Labour Charge				
	Panel Beating			~~$700.00~~	350
	Spray Paint			~~$600.00~~	500
	Check lighting			~~$60.00~~	30
	TOTAL LABOUR			$1,360.00	
	ESTIMATE TOTAL			$4,285.96	

NA2 LKK
17/2/2021 1630
PIP
2 DAYS
CHECK ITEM PHOTOS
BEFORE PAINT PHOTOS

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: