CYCLE & CARRIAGE

Exceptional Journeys

Surveyor :	STEVE LKK
Claim :	AIG OD
DOA :	06.03.2021
Emailed :	25.05.2021, 1.45pm
Date Survey :	10.03.2021

VEHICLE NO : SMM 1088 T

MODEL : KIA CERATO 1.6 A SR SX

WIP : 30266

Material	: $	4,031.20
Labour	: $	5,110.00
Sub-Total	: $	9,141.20
	: $	-
Less Excess	: $	300.00
Total	: $	8,841.20
GST 7%	: $	618.88
Grand Total	: $	9,460.08
Finalise By/Date	:	LOI / 25/05/2021

[✓] REVERT BACK WITHIN 7 DAYS,
OTHERWISE WILL PROCEED WITH INVOICING

[ ] SURVEYOR'S REPORT REQUIRED

[ ] REPAIR TOOK 0 WORKING DAYS + 0 Days (0) Weekends
+ 0 Days (0) Public Holiday
TOTAL DAYS REPAIR TOOK = 0

[ ] TP claim

[ ] Claim GIA / LTA fee

[ ] Claim Loss of [ ] Use / [ ] Rental

[ ] Claim Medical Fee / Others

[ ] Third Party Report -

CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240

KIA

PRO-FORMA INVOICE

Co Reg No : 199405410K **THIS IS NOT AN OFFICIAL TAX INVOICE** GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 **Contact No** 64191000 10/03/2021	**Cust No/Name**	LCV10710/KEK LIET SHENG, JUSTIN (GUO LIE
	Reg No/Reg Date	SMM1088T / 30/07/2019
	Date In/Mileage	10/03/2021/ 34239
	Chassis/Package	KNAF3416MK5047682
	Engine No	G4FGKH741997
	Make/Model	KIA/CERATO 1.6 A SR SX G335
	Colour/Trim	ABT PLATINUM GRAPHI/ WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
LAX00000	Credit	25/05/2021/ 13:30	BLK	260 / AiTing	30266

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
E PNT88000 REPLACE DAMAGED PARTS, REPLACE FRONT BUMPER, LH FRONT FENDER, FRONT H/LAMP SUPPORT PANEL, REPAIR ALL OTHER AFFECTED AREAS, ADJUST AND ALIGN BODY GAPS ALIGNMENT TO THE SAME				1600.00
E PNT98000 RESPRAY ON FRONT BUMPER, LH FRONT FENDER, LH FRONT INNER FENDER, LH FRONT DOOR, LH SIDE SILL, BONNET, AND ALL OTHER AFFECTED AREAS TO THE SAME				1750.00
E PNT88000 REMOVE & INSTALL FRONT PARKING ASSIST TO FACILITATE REPAIR				80.00
E PNT88000 REMOVE & INSTALL RADIATOR, & A/COND CONDENSER TO FACILITATE REPAIR				120.00
A WHEELALIGNMENTBP CONDUCT COMPUTERIZE FULL WHEEL ALIGNMENT				120.00
M SUNDRY PERFORM RUST PREVENTION ON AFFECTED AREAS				40.00
A 54900099 CHECK WIRING & CHASSIS ELECTRICAL SYSTEM				30.00
A 10028901 CONDUCT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST AND CLEAR TROUBLE CODE				120.00
M SUNDRY SUNDRIES				20.00
E PNT88000 REPAIR ON LH FRONT WHEEL HOUSING, LH SIDE SILL, LH FRONT A PILLAR, LH FRONT DOOR				600.00
E PNT98000 RESPRAY ON LH FRONT A PILLAR				350.00
A 10028901 REPAIR ON FRONT WIRING				200.00
S SPECIALISTJOB VACUUM & TOP UP A/COND GAS				80.00
X EXC INSURANCE EXCESS				-300.00

Rupp

Pro Forma

This is not an official tax invoice.
This is a computer generated document, no signature is required.

CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240

KIA

PRO-FORMA INVOICE

Co Reg No : 199405410K **THIS IS NOT AN OFFICIAL TAX INVOICE** GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 **Contact No** 64191000 10/03/2021	**Cust No/Name**	LCV10710/KEK LIET SHENG, JUSTIN (GUO LIE
	Reg No/Reg Date	SMM1088T / 30/07/2019
	Date In/Mileage	10/03/2021/ 34239
	Chassis/Package	KNAF3416MK5047682
	Engine No	G4FGKH741997
	Make/Model	KIA/CERATO 1.6 A SR SX G335
	Colour/Trim	ABT PLATINUM GRAPHI/ WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
LAX00000	Credit	25/05/2021/ 13:30	BLK	260 / AiTing	30266

	Description of Goods / Services	Qty	Unit Price	Disc%	Amount
X	LAMP ASSY-HEAD,LH	1.00	2210.00	20.00	1768.00
X	CARRIER ASSY-FRONT END MODULE	1.00	675.00	20.00	540.00
X	INSULATOR-FENDER LH	1.00	27.00	20.00	21.60
X	PANEL-FENDER,LH	1.00	430.00	20.00	344.00
X	GUARD ASSY-FRONT WHEEL,LH	1.00	95.00	20.00	76.00
X	GARNISH-RADIATOR GRILLE	1.00	38.00	20.00	30.40
X	COVER-FR BUMPER	1.00	633.00	20.00	506.40
X	LAMP ASSY-SIDE REPEATER,LH	1.00	143.00	20.00	114.40
X	BRACKET-FR BUMPER UPR SIDE MTG	1.00	22.00	20.00	17.60
X	ORNAMENT-KIA NO.115	1.00	32.00	20.00	25.60
X	MOULDING-FRONT BUMPER,LH	1.00	216.00	20.00	172.80
X	CLIP	7.00	1.00	20.00	5.60
X	COOLANT (4L) Supp	1.00	26.00	20.00	20.80
X	GRILLE-FRONT BUMPER	1.00	? 485.00	20.00	388.00
Z	TEXT				
	AIG OD CLAIM				
	DOA :06.03.2021				
	SURVEYOR : STEVE LKK				
	10 DAYS + 02 DAYS = 12 DAYS				

Pro Forma

Guarantee Your Warranty, Maintain with Cycle & Carriage!

Parts	4,031.20	**Nett**	8,841.20
Labour	4,970.00	7% GST on 8841.20	618.88
Standard Menu	0.00		
Specialist Job	80.00	**Total Payable**	9,460.08
Diagnostics Job	0.00		
Sundry/Others	-240.00		
Total(w/o GST)	8,841.20		

This is not an official tax invoice.
This is a computer generated document, no signature is required.

CYCLE & CARRIAGE | Exceptional Journeys

INSURANCE CO. : **AIG**

Supplementary Parts For Registration No.: **SMM 1088 T**

	Materials	**Cost ($)**
1	Moulding-front bumper, LH	216.00
2	Clips (x7)	7.00
3	Coolant (4L)	26.00
	Total Materials	249.00
	Less 20% discount	49.80
	Total after discount	199.20

	Labour	**Cost ($)**
1	Repair on LH front wheel housing, LH side sill, LH front a pillar, LH front door ($400 + $200)	600.00
2	Respray on LH front A pillar	350.00
3	Repair on front wiring	200.00
	Total labour	1,150.00
	Total amount	1,349.20
	7% GST	94.44
	Grand total	**$ 1,443.64**

Thank You.
Yours faithfully

LOI AI TING
SENIOR OFFICER - ADMIN
KIA SERVICE CENTRE
DID : 6568 4556 / 6568 4501
FAX : 6567 5258 / 6565 1240

CAR NO: SMM 1088T

WIP: 30266 (ADDITIONAL PARTS CHANGE)

S/NO	PARTS NAME	? / SUPP	CSA SIGN	PHOTO TAKEN	REMARKS
1	Repair Frt LH wheel housing $400	? / SUPP		✓	Steve 10/3/21
2	Painting Frt LH A-pillar $350	? / SUPP		✓	
3	Insulator - Fender LH	? / SUPP		✓ CRU	
4	Grille - Front Bumper	? / SUPP		✓ CHY (Black)	
5	Moulding Assy - Fr Bumper LH	? / SUPP		✓ CHT	
6	Clip - Front Bumper X10	? / SUPP		✓ NCC	
7	Radiator Coolant	? / SUPP		✓ NRC	Steve 11/3/21
8	Repair "A" pillar LH, Front door LH +	? / SUPP		✓	
9	LH side sill $200	? / SUPP		✓	
10	Repair Frt wiring $200	? / SUPP		✓	
11	Add 2 repair days - total 12 days	? / SUPP			
12		? / SUPP			
13		? / SUPP			
14		? / SUPP			
15		? / SUPP			
16		? / SUPP			
17		? / SUPP			
18		? / SUPP			
19		? / SUPP			
20		? / SUPP			

	DATE	TAKEN BY
PHOTO BEFORE PAINT		
PHOTO AFTER PAINT		
PHOTO OF MOUNT TO CELLLETE BENCH		
REMOVE AND INSTALL ENGINE		
REMOVE AND INSTALL DASHBAORD		
REMOVE & INSTALL FUEL TANK		
PHOTO UNDERCARRIAGE PARTS		

MODEL: Cerato 1.6 SX

SURVEYOR: Steve - LKK

Work Order: R001387
License: smm 1088 t
Technician: 810119 kfsan
Mileage: 34241
Date 24.3.21 17:26

Kia : Cerato/Forte : 2019- (BD/BDm) : without Independent Rear Suspension : Rest of World

	Front : Left			Front : Right		
	Actual	Before	Specified Range	Actual	Before	Specified Range
Camber	-0°32'	-0°31'	-0°53' 0°07'	-0°40'	-0°40'	-0°53' 0°07'
Caster	4°15'	4°15'	4°00' 5°00'	5°11'*	5°11'*	4°00' 5°00'
Toe	0°03'	0°03'	-0°03' 0°09'	0°02'	0°02'	-0°03' 0°09'
SAI	11°15'*	11°14'*	13°30' 14°30'	12°27'*	12°27'*	13°30' 14°30'
Included Angle	10°44'*	10°44'*	12°37' 14°37'	11°47'*	11°47'*	12°37' 14°37'
Turning Angle Diff.						

Front

	Actual	Before	Specified Range
Cross Camber	0°08'	0°09'	
Cross Caster	-0°57'	-0°57'	
Cross SAI	-1°11'	-1°12'	
Total Toe	0°05'	0°05'	-0°06' 0°18'
Cross Turn Diff.			

	Rear : Left			Rear : Right		
	Actual	Before	Specified Range	Actual	Before	Specified Range
Camber	-0°56'	-0°56'	-1°42' -0°42'	-1°32'	-1°32'	-1°42' -0°42'
Toe	0°06'	0°07'	-0°02' 0°16'	0°07'	0°07'	-0°02' 0°16'

Rear

	Actual	Before	Specified Range
Cross Camber	0°36'	0°36'	
Total Toe	0°14'	0°14'	-0°04' 0°32'
Thrust Angle	0°00'	0°00'	

* This value is not within specification. Tire wear, handling and safety problems may result.

WinAlign 12.1 B896 International 2021.0.1 Hx421

KDS KNAF3416MK5047682

VDN : 210325018I
03/25/21 09:28

HOME Online CERATO/FORTE../2019/G 1.6 MPI.. VCI

Fault Code Searching

Rescan | Erase All DTC | Go to DTC | Save

ICU CLU WPC

12/12

System	Status	Result
ENGINE	No Current DTC	Good
AT	No Current DTC	Good
ABSESC	No Current DTC	Good
AIRBAG	No Current DTC	Good
AIRCON	No Current DTC	Good
EPS	No Current DTC	Good

System	DTC	Description	State
No Current DTC			

S/W Ver.	M-E-K-01-00-0241	VCI Ver.	02.51
ECU Ver.	M-E-K-01-00-0182	OS Ver.	Android 10