CS3/LPC21000224/Gqd3-1

QCL.
PRS
CPC

ASSIGNMENT

Date:	Veh No: SKA6187U Date: 17 Mar 2021 (2021)
Estimated Cost	Type: M Car / M Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or
OD / TP / WS / TP RES / OD RES / EVA / INV / MV	
Inspect Vehicle No:	Make: Toyota Previa cc 2362
Workshop m/s: Hup Ley Huat	Colour: Silver A/C: Insured / Std / Nil / NA
	Sp Reading: 150983 T/Radio: Insured / Std / Nil / NA
Insured:	Eng/No:
Policy No.	C/No: JTEGD54M30A026773
Claims No: 20/21/21/VC00/024082	Gen Cond: Good / Fair / Poor / Burnt
Sum Insured: Excess:	Steering: Inorder / Jammed / Leaked / Burnt or
(Client's Record)	Brake: Inorder / Jammed / Leaked / Burnt or
Make of Veh:	Modi: Nil / S/Rim / STD A/Rim or
	Tyre Size: F: 215/60R16 R: "
(Policy Condition)	
Remark: The veh had commenced its repair at the time of inspection. (N/S / O/S: O)	BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or Kapsen
Val. or Market Value: $ ~~21K~~ 24K	Front / Rear
DAC Accident Rport: Consistent? : Yes or No	R/Bal 6 mm / R/Bal 6 mm
SIA / PR Seen: Consistent? : Yes or No	L/Bal 6 mm / L/Bal 6 mm
Est. Repairs: 5 days Res.: Yes or No	D.O.A. / D.O.I. 11-01-21
Lum Sum: % 3 Val: Yes or No	Survey held at: W/S 4:30pm
CA / REV / REP. / 24 HRS	Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
Vehicle: IN / OUT	
Date: Person Contacted:	The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	Cot: 18952
	$4000 - $5000
27/04/21	Submit LS $4600, 5 days (Red $2300, 33%)

Date/Time. File Pass to: [ ] Preli. Report

27/04 Typist [ ] Final Report

Date/Time. File Return to:

Days Of Repair: 5

Resurvey No. of Trip:

Survey Fee:

Transportation

Add Fee: [ ] Site Insp: $ [ ] Interview: $

TP

Total Sum: 4600