# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R




## PRE-REPAIR INSPECTION REPORT

SOMPO INSURANCE SINGAPORE PL

50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWER SINGAPORE 048623

Ref: CS3/SMO21003473/GUtd3e2

Date: 05/04/2021

Code: SMO

### 1. Policy Particulars :- (THIRD PARTY CLAIM)

| | | | | |
|---|---|---|---|---|
| | **Insured Veh.** | GBD 2708J | **Veh. Inspected** | YQ 393E |
| | **Policy No.** | | **Coverage ($)** | 0.00 |
| | **Claim No.** | CMTD2100813 | **Excess ($)** | 0.00 |
| | **Assign From** | MELVIN YE YONG KANG | **Assign Date** | 16/03/2021 |

### 2. Vehicle Particulars & Condition

| | | | | |
|---|---|---|---|---|
| | **Make & Model** | ISUZU NPR75UH5A | **c.c** | 5193 |
| | **Engine No.** | HIDDEN | **Year of Reg.** | 2019 |
| | **Chassis No.** | JAANPR75HJ7103379 | **Colour** | WHITE |
| | **Odometer** | 22162 KM | **Steering** | IN ORDER |
| | **Brakes** | IN ORDER | **Modification** | NIL |
| | **General** | GOOD | | |

### 3. Conditions of Tyres

| | | **Size** | **Make** | **Balance** |
|---|---|---|---|---|
| | **R/H Front Tyre** | 215/75 R17.5 | BRIDGESTONE | 6 mm |
| | **L/H Front Tyre** | 215/75 R17.5 | BRIDGESTONE | 6 mm |
| | **R/H Rear Tyre** | 215/75 R17.5 (D) | BRIDGESTONE | 6/6 mm |
| | **L/H Rear Tyre** | 215/75 R17.5 (D) | BRIDGESTONE | 6/6 mm |

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.



### 5. General Information

| | | | | |
|---|---|---|---|---|
| | **Accident Date** | 13/03/2021 | **Inspect Date / Time** | 18/03/2021 ( 11:11 AM ) |
| | **Survey held at** | GARAGE 13 PTE LTD<br>8 KAKI BUKIT AVE 4 #03-46 PREMIER 415875 SINGAPORE. | | |

### 5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.
D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF $3,000-$4,000

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **4 Working Days**

Report Ref No. CS3/SMO21003473/GUtd3e2

**Inspected By**

**CHUA KANG SENG**

**Licensed Appraiser**

**K.K.LAU CPT(RET)**

**BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE**

**REGD Auto Consultant-SAE, Licensed Appraiser**


**DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.**

**No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.**