CYCLE & CARRIAGE

# CYCLE & CARRIAGE KIA PTE LTD
## PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240

KIA

Co Reg No : 199405410K

## ESTIMATE

GST Reg No : MR-8500111-X

| Invoice Name & Address | Owner Name & Vehicle Info | |
|---|---|---|
| LAU GUEK MING (LIU YUEMING) | Cust No/Name | LCV13266/LAU GUEK MING (LIU YUEMING) |
| 32 WOODLANDS DRIVE 16 | Reg No/Reg Date | SMW3526E / 17/11/202 |
| #09-25 | Date In/Mileage | / 0 |
| SINGAPORE 737770 | Chassis No | KNAF3416ML5070188 |
| | Engine No | G4FGKH756647 |
| Contact No | Make/Model | KIA/CERATO 1.6 A EX G333 |
| | Colour/Trim | BBL HORIZON BLUE / WK SATURN BLACK |

| Account No | Terms | Date/Time Printed | CSE | Operator | WIP No |
|---|---|---|---|---|---|
| LCV13266 | CRDVCH | 29/03/2021/ 14:53 | | 442 / CocoLu | 31257 |

| Description of Goods / Services | Qty | Unit Price | Disc% | Amount |
|---|---|---|---|---|
| E PNT88000 | | | | 400 1600.00 |
| RENEW FRT BUMPER, FRT SUPPORT PANEL, REPAIR BONNET | | | | |
| E PNT98000 | | | | 350 700.00 |
| SPRAY PAINT FOR FRT BUMPER, BONNET | | | | |
| M SUNDRY | | | | 50.00 X |
| FRT NUMBER PLATE WITH FRAME | | | | |
| A 90000001 | | | | 30.00 |
| CHECK WIRING & ELECTRICAL SYSTEM | | | | |
| A 10028901 | | | | 120.00 |
| TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST | | | | |
| USING HI-SCAN PRO TEST | | | | 20 40.00 |
| M SUNDRY | | | | |
| Sundry | | | | |
| M COVER-FR BUMPER BR | 1.00 | 633.00 | 00.00 | 633.00 |
| M GRILLE-FRONT BUMPER X NM | 1.00 | 262.00 | 00.00 | 262.00 |
| M GRILLE ASSY-RADIATOR X NM | 1.00 | 328.00 | 00.00 | 328.00 |
| M MOULDING-FRONT BUMPER,LH X NM | 1.00 | 36.00 | 00.00 | 36.00 |
| M ABSORBER-FRONT BUMPER ENERGY BR | 1.00 | 84.00 | 00.00 | 84.00 |
| M BRACKET-FR BUMPER UPR SIDE MTG X NM | 1.00 | 22.00 | 00.00 | 22.00 |
| M LAMP ASSY-HEAD,LH X NM | 1.00 | 1219.00 | 00.00 | 1219.00 |
| M BEAM COMPLETE-FR BUMPER OR | 1.00 | 497.00 | 00.00 | 497.00 |
| M CARRIER ASSY-FRONT END MODULE X NM | 1.00 | 675.00 | 00.00 | 675.00 |
| M ORNAMENT-KIA NO.115 NC | 1.00 | 32.00 | 00.00 | 32.00 |

Estimate

Steve CLKK 29/03/21, 3.00pm
OD- NM AL
Excess - ?
P/P
NM BCL
3 days

LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
- To display damaged parts/ parts during resurvey
- Repairs are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Confirm & accepted by

Authorized signatory and company stamp

| | | |
|---|---|---|
| Nett | | 6,328.00 |
| 7% GST on | 6328.00 | 442.96 |
| Total Payable | | 6,770.96 |

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.