PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE	:	ACCIDENT REPAIRS
WORKSHOP	:	UBI ROAD 1
CONTACT NO	:	6366 2323
FAX NO	:	6841 1183
REFERENCE	:	PA/OD/0266/2021/HR
DATE	:	27-Mar-21
WIP	:	21373

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 31/3/21

AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120
Attn: Motor Claims Dept
Tel: 6880 4602 - Fax: 6880 4838

Hi Adrian
5 days - ok - Johnny Boo
31-May-21

OWNER'S NAME	:	MR. QUEK SIAK KHAI
ADDRESS	:	7 AMBER GARDENS #09-15 SINGAPORE 439974
TELEPHONE	:	HP +65 97353768
TYPE OF CLAIM	:	OWN DAMAGE CLAIM
POLICY NO	:	2100496062-04
VEHICLE NO	:	**SCH 2328 P**
MODEL CODE	:	A6 1.8 TFSI S TRONIC
MODEL YEAR	:	29/12/2016
ENGINE NO	:	CYG 015280
CHASSIS NO	:	WAUZZZ4G0HN011701
MILEAGE	:	-
DATE IN	:	-
ESTIMATED BY	:	JOHNNY BOO / ALLAN WU
ACCIDENT DATE	:	27-Mar-21
PLACE OF ACCIDENT	:	LOR 2 TOA PAYOH

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SCH 2328 P

S/N	NATURE OF JOBS			ESTIMATED CHARGES		*SURVEYOR'S RECOMMENDATIONS*
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N	$	480.00	*$*	*480.00*
2	TO REMOVE AND TRANSFER RHS HEADLIGHTS'S CONTROL UNIT AND POWER MODULE.	S/N	$	400.00	*$*	*250.00*
3	TO DISMANTLE AND RENEW FRONT BUMPER, RHS FRONT FENDER, BONNET AND RHS HEADLIGHT. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.		$	3,200.00	*$*	*1,000.00*
4	TO RESPRAY FRONT BUMPER, FRONT BUMPER LOWER SPOILER, RHS FRONT FENDER AND BONNET.		$	3,500.00	*$*	*1,650.00*
5	TO CARRY OUT DIAGNOSTIC CHECK.	S/N	$	192.00	*$*	*192.00*
	TOTAL LABOUR CHARGES	:	**$**	**7,772.00**	*$*	*3,572.00*

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SCH 2328 P

			DAMAGED PARTS & PRICES			
S/N	PARTS DESCRIPTION	QTY		S/NETT		*REMARKS*
1	FRONT BUMPER	1	$	3,268.00	$	2,614.40
2	FRONT BUMPER FIXING PARTS	1	$	543.00		
3	FRONT BUMPER LOWER GRILLE - CENTER	1	$	128.00		
4	FRONT BUMPER LOCKING CLIP	14	$	55.00		
5	FRONT BUMPER ADAPTER	1	$	38.00	$	29.84
6	FRONT BUMPER CLOSING ELEMENT	1	$	219.00		
7	FRONT BUMPER LOWER SPOILER	1	$	249.00		
8	FRONT BUMPER SHORT SPOILER	1	$	945.00		
9	FRONT RADIATOR GRILLE	1	$	1,934.00		
10	FRONT RADIATOR GRILLE COVER	1	$	36.00		
11	FRONT RADIATOR AIR GUIDE GRILLE - RH	1	$	496.00		
12	FRONT RADIATOR COVER - RH	1	$	51.00		
13	FRONT WHEEL SPOILER - RH	1	$	264.00	$	211.20
14	FRONT BUMPER SIDE REINFORCEMENT	1	$	872.00		
15	FRONT BUMPER FOAM FILLER PIECE	1	$	237.00		
16	FRONT BUMPER GUIDE BRACKET - RH	1	$	38.00	$	29.84
17	FRONT BUMPER REINFORCEMENT COVER	1	$	123.00		
18	"CAUTION" STICKER	1	$	14.00		
19	FRONT PARKING AID OUTER SENSOR	1	$	244.00		
20	FRONT HIGH TONE HORN - RH	1	$	201.00		
	SUB TOTAL SPARE PARTS	:	**$**	**9,955.00**	$	2,885.28

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APROVED
SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SCH 2328 P

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES S/NETT	REMARKS
	c/f			*$ 2,885.28*
21	FRONT HIGH TONE HORN SPRING SHACKLE - RH	1	$ 47.00	
22	FRONT FENDER - RH	1	$ 1,391.00	*$ 1,112.80*
23	FRONT FENDER ATTACHMENT PARTS - RH	1	$ 102.00	
24	FRONT FENDER STONE GUARD FILM - RH	1	$ 121.00	*$ 96.40*
25	FRONT FENDER BRACE	1	$ 96.00	*$ 76.48*
26	FRONT BONNET	1	$ 5,436.00	
27	FRONT BONNET ATTACHMENT PARTS	1	$ 178.00	
28	HEADLIGHT MOUNTING - RH	1	$ 118.00	
29	HEADLIGHT - RH	1	$ 9,540.00	*$ 7,632.00*
30	HEADLIGHT LIFT CYCLINDER - LH	1	$ 236.00	
31	FRONT WHEEL HOUSING LINER - RH	1	$ 275.00	
32	FRONT WHEEL HOUSING LINER ATTACHMENT PARTS - RH	1	$ 73.00	
33	FRONT NUMBER PLATE	S/N	$ 60.00	
34	*Added parts - see attached*		*$ 68.00*	*$ 53.44*
35	SUNDRIES		$ 250.00	*$ 5.12*
	TOTAL SPARE PARTS	:	**$ 27,946.00**	*$ 11,861.52*
	TOTAL LABOUR CHARGES	:	**$ 7,772.00**	*$ 3,572.00*
	GRAND TOTAL	:	**$ 35,718.00**	*$ 15,433.52*

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APROVED
SPARE PARTS ARE SPECIAL NETT.
BL-04/05/21

PREMIUM AUTOMOBILES
55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183
Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Supplementary Estimate

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept **Tel: 6841 0055 / Fax: 6256 4315**	**Estimate No.** **Date** **Service Advisor** **Pages** **Regn No** **Model No**	PA/OD/0266/2021/HR 21-Apr-21 CHANG 1 of 1 SCH 2328 P AUDI A6 1.8 TFSI

Quantity	Description	Unit Price	Amount
Parts			
1	FRONT BUMPER ADAPTER - LH	$ 38.00	***$ 29.84***
2	FRONT BUMPER BRACE - RH	$ 30.00	***$ 23.60***
	GRAND TOTAL	**$ 68.00**	***$ 53.44***

For Premium Automobiles Pte Ltd

Authorised Signature

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT