

Trans-cab Auto Services Pte Ltd.

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD813E**AAD2104-***Not Authorised
L/Smp \$1500/r*

Vehicle No.:
Chassis No.:
Vehicle Make:
Vehicle Model:
Date of Accident :
Third Party Insurer :
Date of Registration :

12 APR 2021**SHD813E**

WDD2120012B224840

MERCEDES

MB E 220 BLUE TEC

06/04/2021

AIG

16/12/2015

PART
1510.00

1 Rear Bumper
1 Rear Bumper Lower
1 Rear Bumper Centre Pad
1 Rear Bumper Side Pad
1 Rear Bumper Tow Hook Cover
1 Rear Bumper Bracket
1 Rear Bumper Side Retainer Bracket
1 Rear Bumper Inner Frame
1 Rear Bumper Bottom Bracket
1 Rear Bumper Top Bracket
1 Rear Bumper Side Holder Bracket
1 Rear Bumper Inner Bracket LH
1 Rear Bumper Inner Bracket RH
1 Rear Bumper Beam
1 Rear Bumper Beam Bracket LH
1 Rear Bumper Beam Bracket RH
1 Rear Bumper Bracket Centre
1 Rear Bumper Retainer Bracket LH
1 Rear Bumper Retainer Bracket RH
1 Rear End Panel Outer
1 Rear End Panel Inner Trim

LIST
Bumper

\$	3,105.00	✓
\$	1,080.00	X
\$	307.83	X
\$	186.33	X
\$	63.00	X
\$	22.50	X
\$	132.00	✓
\$	297.00	X
\$	60.00	X
\$	129.00	X
\$	135.00	X
\$	198.00	X
\$	198.00	X
\$	1,215.00	X
\$	307.50	} X
\$	307.50	
\$	461.75	
\$	202.50	
\$	202.50	
\$	1,971.00	
\$	630.00	
\$	11,211.41	
10% \$	1,121.14	
\$	10,090.26	

Special Nett

1SET PARKING AID
1SET REAR BUMPER CLIP

TOTAL \$ 700.00 X
\$ 66.00 ✓

Trans-cab Auto Services Pte Ltd**AAD2104-**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD813E

1SET RIM	\$	<i>Per</i> 650.00	}	<i>X</i>
1SET BUMPER BRACKET CTR CLIP	\$	<i>na</i> 33.00		
1SET BUMPER BRACKET SIDE CLIP RH RR	\$	<i>na</i> 10.00		
1SET BUMPER RETAINER RH CLIP RR	\$	<i>na</i> 20.00		
1SET FENDER CLIP	\$	<i>na</i> 60.00		
1 SET Rear End Panel Inner Trim Clip	\$	<i>na</i> 90.00		
1 SET Rear Bumper Fastener Clip	\$	<i>na</i> 101.54		
TOTAL	\$	1,539.00		
TOTAL PARTS	\$	11,629.26		

LABOUR

Putty And Spray Painting Of The Affected Portion.	\$	3,000.00	<i>2201</i>
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	3,000.00	<i>2001</i>
To Rust-Proofing Of The Affected Areas.	\$	<i>na</i> 170.00	<i>X</i>
To reinstall rear bumper parking sensor.	\$	170.00	<i>601</i>
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	<i>na</i> 170.00	<i>X</i>
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	<i>na</i> 170.00	<i>X</i>
To check steering geometry and computer wheel alignment	\$	<i>na</i> 220.00	<i>X</i>
To Check Electrical Lighting Concerned.	\$	<i>na</i> 170.00	<i>X</i>
TOTAL	\$	7,070.00	

Trans-cab Auto Services Pte Ltd

AAD2104-

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD813E

Over All Total \$ 28,789.53

(LUMP SUM)

Repair Days

20 DAYS

2 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer .

Signature:

Date: