CS3/AGI21001667/Eqd3e2-1

ASS. REC. BY: Steve | REF: ~~CS/AGI21001667/Eqd3~~

ASSIGNMENT

From: PRS Date:
Estimated Cost:
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
To Inspect Vehicle No: SKE 3507D
at Workshop m/s K'S PERFORMANCE
of
Insured: SLF 1282Y
Policy No.
Claims No. C10008561/KY
Sum Insured: Excess:
(Client's Record)
Make of Veh:

(Policy Condition)
Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:
IDAC Accident Rport: Consistent? : Yes or No
GIA / PR Seen: Consistent? : Yes or No
Est. Repairs: 3 days Res.: Yes or No
Lum Sum: 20 % 3 Val.: Yes or No
CA / REV / REP. / 24 HRS
Vehicle: IN / OUT
Date: Person Contacted:

Veh No: SKE 3507D Yr Regn: 31/5/10
Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or
Make: Toyota Camry c.c 1998
Colour: Gy A/C: Insured / Std / Nil / N
Sp.Reading: 301453 T/Radio: Insured / Std / Nil / N
Eng/No:
C/No: MR053BK410 7057659
Gen. Cond: Good / Fair / Poor / Burnt
Steering: Inorder / Jammed / Leaked / Burnt or
Brake: Inorder / Jammed / Leaked / Burnt or
Modi: Nil / S/Rim / STD A/Rim or
Tyre Size: F: 215/60R16
R:
BS / DUN / EXNOVA / GY / FS / LIZAJ MIC / OHTSU / PIR / SUMI / TOYO / YOKO or Firen 29

Front			Rear		
R/Bal.	4	mm	R/Bal.	4	mm
L/Bal.	4	mm	L/Bal.	4	mm

D.O.A. 1/1/21 D.O.I. 5/2/21
Survey held at ~~Cycle & Carriage~~
Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or F+ R11
The U/C / Chassis frame / Body Structure affected due to collision

Date / Time	Action / Instruction
	MV-36K
	Estimate COR: $3000-$4000
	Submit PRS.
19/4/21	STEVE FINALISED L/S $2000, 3 DAYS. (RED $2700; 57%)

Date/Time, File Pass to? : Preli. Report
19/4 TYPIST : Final Report
Date/Time, File Return to?

Days Of Repair: 3
Resurvey No. of Trip:

Add Fee: : Site Insp ($)
: Interview ($)
: Tech. Invs ($)
: Weekend ($)

Survey Fee:
Transportation:
S + RS, SI
Photos
Others
TOTAL

Informed : TP
Lump Sum / Estimate: $2000.00