CAB PTE LTD

EPAIR ESTIMATE*

VEHICLE NO SHA9971M

MAKE :

MODEL IONIQ G3

15/04/21

CHIANG/NTUC

Qty	Parts Description/ Labour	Type		Amount
1	REAR BUMPER			$459.40
1	REAR BUMPER CENTRE MOULDING			$451.25
1	REAR BUMPER SIDE BRACKET RH			$55.80
10	REAR BUMPER COVER CLIPS		$2.20	$22.00
1	REAR BUMPER RH UNDER COVER			X $108.00
1	REAR IONIQ EMBLEM			$24.30
1	REAR HIBRID EMBLEM			$31.30
1	REAR BUMPER COVER TOWING			X $98.80
1	REAR RH- BLIND SPOT RADAR			X $1,625.00
1	REAR BUMPER REFLECTOR RH			$41.45
	SUB TOTAL		1085.50	**$2,917.30**
	20.00%		868.40	**$583.46**
	DISCOUNTED TOTAL			**$2,333.84**
1	REAR REVERSE SENSOR			X $180.00
1	BOOTLID COMFORT LOGO & TEL NO.STICKER		60	$60.00
		10.00%	54	**$216.00**
	Labour Charge			
	Panel Beating		350	$760.00
	Spray Painting Charge		300	$600.00
	Tuff Kote			X $90.00
	Diagnose/Rest error code		Report. 180	X $280.00
	Remove/refix Reverse sensor		30.	$60.00
	TOTAL LABOUR		880.	**$1,790.00**
	ESTIMATE TOTAL		$1802.40	**$4,339.84**
			2 days	

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Tanphin 97415749
up' 14/4/21 c 4.30
L/S Resurvey after up
Tanphin c/Microfo.com
2 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Co