(08/11/13) wef

ASS. REC. BY: Marcus

REF: CC6/AIG21005153/UPS3

ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SKT8528C

at Workshop m/s Tan Lim

of

Insured: GBF8043T

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: $50k

IDAC Accident Rport: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS INTE

Vehicle: IN / OUT

Date: Person Contacted: Dep 10k.

Veh No: SKT8528C Yr Regn: 25/6/15

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or CA /

Make: Toyota Corolla AHXI c.c 1598

Colour Silver A/C: Insured / Std / NI / NA

Sp.Reading 185258 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: MR053REH104534841

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi : Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/55-R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or Achilles

Front		Rear	
R/Bal.	6 mm	R/Bal.	mm
L/Bal.	6 mm	L/Bal.	6 mm
D.O.A.	23/4/21	D.O.I.	27/4/21

Survey held at

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or Rear O/S &

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	L/A $37500 3/4 yrs 2mth
	NOTT $12500

Date/Time, File Pass to? ☐ : Preli. Report

1) ☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee: ☐ : Site Insp ($) __S + RS, __SI

☐ : Interview ($) Photos

☐ : Tech. Invs ($) Others

☐ : Weekend ($)

Report Format :

Lump Sum / I.B.I: ($)

TOTAL