ASS. REC. BY: Steve | REF: ~~CS3/LPC20012639/Eqf3~~

CS3/LPC20012639/Eqf3-1

ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No. 20/20/20/VC05/023910

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S | O/S

Bal. or Market Value:

IDAC Accident Rport: Consistent? : Yes or No

SIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 4 days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SMS 5345T Yr Regn: 28/2/20

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: Honda Vezel c.c 1496

Colour Black A/C: Insured / Std / NI / N

Sp.Reading 47632 T/Radio: Insured / Std / NI / N

Eng/No:

C/No: RU1-1329076

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl : NII / S/Rim / STD A/Rim or

Tyre Size: F: 215/60R16

R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or $

Front		Rear	
R/Bal.	4 mm	R/Bal.	4 mr
U/Bal.	4 mm	U/Bal.	4 mr
D.O.A.	13/11/20	D.O.I.	17/11/20

Survey held at Garage 13

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or Rear LH

The U/C / Chassis frame / Body Structure affected due to collisio

Date / Time	Action / Instruction
	MV-89K
10/05/21	Submit LS $1650, 4 days (Red $1150, 41%)

Date/Time, File Pass to? 10/05 Typist

Date/Time, File Return to?

☐ : Prell. Report

☐ : Final Report

Days Of Repair: 4

Resurvey No. of Trip:

Add Fee: ☐ : Site Insp ($)

☐ : Interview ($)

☐ : Tech. Invs ($)

☐ : Weekend ($)

Rep Format : TP

Lump Sum Fee : 1650

Survey Fee:

Transportation: S + RS SI

Photos

Others

TOTAL