# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PRE-REPAIR INSPECTION REPORT

AXA INSURANCE PTE LTD		Ref:	CS3/ASM21005544/Euce2
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811		Date:	18/05/2021
ATTN: KHOR SAW THENG		Code:	ASM

1.	Policy Particulars :- (THIRD PARTY CLAIM)		
Insured Veh.	SHA 2344U	**Veh. Inspected**	SLN 5281G
Policy No.		**Coverage ($)**	0.00
Claim No.	S1M039K5	**Excess ($)**	0.00
Assign From	KHOR SAW THENG	**Assign Date**	06/05/2021

2.	Vehicle Particulars & Condition		
Make & Model	TOYOTA ALTIS	**c.c**	1598
Engine No.	HIDDEN	**Year of Reg.**	2017
Chassis No.	MR053REH104557649	**Colour**	BLACK
Odometer	148572 KM	**Steering**	IN ORDER
Brakes	IN ORDER	**Modification**	SPORTS RIM
General	GOOD		

3.	Conditions of Tyres		
	Size	**Make**	**Balance**
R/H Front Tyre	215/45 R17	YOKOHAMA	4 mm
L/H Front Tyre	215/45 R17	YOKOHAMA	4 mm
R/H Rear Tyre	215/45 R17	YOKOHAMA	4 mm
L/H Rear Tyre	215/45 R17	YOKOHAMA	4 mm

4.	Description of Damages
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.	

5.	General Information		
Accident Date	06/05/2021	**Inspect Date / Time**	06/05/2021 (05:00 PM)
Survey held at	14 ANG MO KIO STREET 63 BLK B SINGAPORE 569116		
Repairer	ASSURE AUTO ASSIST PTE LTD		

5a.	Remarks
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF $3,000-$4,000	

5b.	Estimate Days of Repair
ESTIMATED NORMAL PERIOD FOR REPAIR: **5 Working Days**	

Report Ref No. CS3/ASM21005544/Euce2

Inspected By

CHEN TSUE YEE

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser