ASSIGNED BY: Tanjin REF: CS3/CT/2100556 4/TIV83

ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured: GBL 242G

Policy No. DMCVSNW00019122100

Claims No. SNM21D202616/C02/TOHHS

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 95K

IDAC Accident Rport: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SBB8228Z Yr Regn: 2016 March

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: Kia Forte K3 c.c 1591

Colour Red A/C: Insured / Std / NI / NA

Sp.Reading 47179 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: KNAFX411MG5579759

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi : Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/55R16

R: " "

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front		Rear	
R/Bal.	6 mm	R/Bal.	6 mm
L/Bal.	6 mm	L/Bal.	6 mm
D.O.A.	5/5/21	D.O.I.	7/5/21 @ 430pm

Survey held at Orion Auto Lite.

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or Frt N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	GIA uploaded in Vivus. Repair Range $2000-$3000, 4 days
11/5/21	Submit PRS, repair range $2000-$3,000

Date/Time, File Pass to? 1) ☐ : Prell. Report ☐ : Final Report

Date/Time, File Return to? 2) 11/5/21-Typist

Report Format : PRS

Lump Sum / [illegible]

Days Of Repair: 4

Resurvey No. of Trip:

Add Fee: ☐ : Site Insp ($) ☐ : Interview ($) ☐ : Tech. Insp ($) ☐ : [illegible] ($)

Survey Fee:

Transportation: S + RS S

Photos

Other:

TOTAL