ASS. REC. BY: Steve CS3/ASM21205818/EVC

ASSIGNMENT

From: PRS Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

at

Insured:

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rport: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Sum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SGS1238S Yr Regn: 31/1/18

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: BMW 520i c.c 1998

Colour: Grey A/C: Insured / Std / Nil / N

Sp.Reading: 74683 T/Radio: Insured / Std / Nil / N

Eng/No:

C/No: WBAJA 1201 0BJ19136

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 245/45 R18

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or Pirelli

Front		Rear	
R/Bal.	5 mm	R/Bal.	5 mm
L/Bal.	5 mm	L/Bal.	5 mm
D.O.A.	14/5/21	D.O.I.	14/5/21, 6-00pm

Survey held at Eng Soon

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or FL RH

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time	Action / Instruction
	MV - 145K repair range 13K - 14K
	6 repair days

Date/Time, File, Pass to? : Prell. Report

: Final Report

Days Of Repair:

Resurvey No. of Trip:

Date/Time, File Return to?

Add Fee: : Site Insp ($)

: Interview ($)

: Tech. Inve ($)

: Weld and ($)

Survey Fee:

Transportation: S + RS S

Photos

Others

TOTAL