ASS. BY: REF: CC4/GRB2100 5883/Des 3

ASSIGNMENT

COE June 2029

From: Date:

Estimated Cost:

OD / TPFWS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured

Policy #

Claims b.

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rport: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 3 days Res.: Yes or No

Lump Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted: Vehicle: IN / OUT

Veh No: SJZ 1951T Yr Regn: June 1992

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: Honda Civic c.c 1595

Colour Red A/C: Insured / Std / NI / NA

Sp.Reading 477372 T/Radio: Insured / Std / NI / NA

Eng/No: B16A2 1007489

C/No: JHMEG6390 0S003782

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi : Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195/55 R15

R: " "

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or Dunlop

Front		Rear	
R/Bal.	S mm	R/Bal.	S mm
L/Bal.	S mm	L/Bal.	S mm

D.O.A. 16/05/2021 D.O.I. 18/05/2021

Survey held at JWG AMC

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or Front

The U/C / Chassis frame / Body Structure affected due to collision.

Date /Time	Action / Instruction
	TU SMR 5916B
14/10/21	finish 2/S 1750/- with 3 days of repair

Date/Time, File Pass to?

1)

Date/Time, File Return to?

2)

☐ : Prell. Report

☐ : Final Report

Days Of Repair:

Resurvey No. of Trip:

Add Fee: ☐ : Site Insp ($)

☐ : Interview ($)

☐ : Tech. Invs ($)

Survey Fee:

Transportation: S + RS SI

Photos

Others

Report Format :