TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722
Tel: 6250 0088 Fax: 6250 5545
Email: operation@tlauto.com.sg
GST No: 201700521W UEN No: 201700521W

M/S : AIG ASIA PACIFIC INSURANCE PTE. LTD.
78 SHENTON WAY #07-16
AIG BUILDING
SINGAPORE 079120

Not authorised
Running B4 paint
4days

ATTN : MOTOR CLAIM DEPT
TEL : 6419 3000 FAX : 6415 3723

YOUR REF NO :
CLAIM TYPE : OWN DAMAGE
ACCIDENT DATE : 11/05/2021

4/6/2021
11/6/2021

ESTIMATE

NO : **QUOT202105-000058(00)**
DATE : 03/06/2021
POLICY NO : 999995580
VEH REG NO : **SMZ3347P**
MAKE/MODEL : MERCEDES BENZ C180 AVANTGARDE (R17 LED)
CHASSIS NO : WDD2050402R326808
ENGINE NO : 27491031121154
REG. DATE : 2017

Estimate Repair Cost to Vehicle No : SMZ3347P

	Description	Quantity	Unit Price S$	Amount S$	
	PARTS				
1	Headlamp assy - LH	1	1,850.00	1,850.00	?
2	Headlamp bracket -- LH	1	68.00	68.00	?
3	Front fender - LH	1	590.00	Bu 590.00	
4	Front fender inner shield - LH	1	98.00	Dij 98.00	
5	Front fender inner shield clips - LH	20	5.50	Nu 110.00	50sn
6	Front bumper	1	MJCM 1,080.00	1,080.00	
~~7~~	~~Front bumper reinforcement~~	~~1~~	~~310.00~~	~~R 310.00~~	~~X~~
8	Front bumper side retainer - LH	1	38.00	CM 38.00	
9	Front bumper sensor	1	138.00	Nd 138.00	
10	Front bumper sensor seals	6	8.00	Nu 48.00	
11	Front bumper clips	15	5.50	Nu 82.50	50sn
				4,412.50	
			Add 10%	441.25	1005N
				4,853.75	
	LABOUR				
12	To remove and refit front bumper sensor	1	100.00	100.00	60
13	To check and rectify wiring system	1	80.00	80.00	20
14	To panel beat and straighten LH front fender inner panel, LH front chassis frame, inncluding replacement of parts and align where necessary , to refit and adjust the same	1	1,200.00	1,200.00	400
15	To putty and spray paint on affected areas	1	800.00	800.00	400
16	To reset and reprograme headlamp fault code	1	350.00	180 ~~350.00~~	?
				2,530.00	1060

$ 3,910.00
10% 391.00
$ 4,301.00

$ 5,461.00
XS 1,700.00
$ 3,761.00
7% 263.27
$ 4,024.27

TOTAL	**S$ 7,383.75**
ADD GST @ 7%	516.86
GRAND TOTAL	**S$ 7,900.61**

SINGAPORE DOLLAR SEVEN THOUSAND NINE HUNDRED AND CENTS SIXTY-ONE ONLY

FOR TONG LUCK AUTO PTE LTD

AUTHORISED SIGNATURE