Surveyor:

REF: CS/CTI19012762/Dtf3-1

Special Instruction:

L/SUM : $ 13,400.00

Third Parties:

Claimant:

Surveyor:

Workshop: Twincar Automotive Pte Ltd

ASSIGNMENT (Office)

From (Person): TEO YI XUAN of CTI Date/Time: 17/6/2021 7:15 PM

Estimated Cost: Bill to:

OD/TP Re-inspection / Evaluation

To Inspect Vehicle No: GBF 7473S Insured: GBD 1148G

at Workshop m/s Twincar Automotive Pte Ltd Tel: 6744 0510

of 2 KAKI BUKIT AVE 2 #01-17 KAKI BUKIT AUTOHUB

Policy No: DMCVSN14238319055 Claim No: SNM19D203300C02

Sum Insured: Excess:

Make of Veh: D.O.A. 13/07/2019

(Client's Record)

H.O.D. Endorsement/Date:

Date/Time: Person Contacted: Vehicle IN / OUT

Date/Time: Confirmed with Final Fig , days (Red $ / %; Original 10 days)

Date/Time: 29/7/2021 Submit Final Fig 6 days (Red $ / %; Original days)

LUMP SUM $6700 6700;50%

Date/Time	Action/Instruction
	GBF 7473S- CS3/CTI19012762/Hcf3e2 DOA : 13/07/2019
	GBD 1148G - CS3/CTI19012762/Hcf3e2 DOA : 13/07/2019
	50/50 billing

Para(1) : Parts found not replaced (To highlight *R or UB, LR, Etc*)

Para(2) : Comments on consistency of damages (Parts Not Consistent : *NC*)

Para(3) : Nett Value

Market Value :

Salvage Value :

Nett Value :

Inspected/ Evaluated by:

Fee Charged:	*Date:*
Basic & Add	
Transport	
Photos	
Others	
Total	

1) Date/Time File Pass to 2) Date/Time File Return to

3) Date/Time File Pass to 4) Date/Time File Return to

5) Date/Time File Pass to 6) Date/Time File Return to