

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

SMR 6423A
TP/AIG

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120

TEL: 64193000

FAX: 64153727

ATTN: Motor Claim Department

Estimate No: ES2190568/YISHUN

Date: 21 Jun 2021

Policy No: D21MTPV01005540

Veh Reg No: SMR6423A

Make/Model: SUBARU SUBARU
FORESTER 2.0XT CVT
AWD SR

WS Ref: TP/AIG

Claim Type: Third Party

Accident Date: 20/06/2021

TP Veh Reg No: SDU7338Y

Chassis No: JF1SJGK85JG099602

Engine No: FA20CB16035

Reg. Date: 25/10/2017

Not Authorised

11 Days &

Presumably After Repair

14 days

Estimate Repair Cost to Vehicle No :SMR6423A

Description	U/Price	Quantity	List Price	Amount
			S\$	S\$
List Price				
1 REAR BUMPER	600.30	1 PC	Br 600.30	✓
2 REAR BUMPER LH REFLECTOR	28.30	1 PC	cm 28.30	✓
3 REAR BUMPER LH SIDE RETAINER	18.30	1 PC	cm 18.30	✓
4 REAR BUMPER REINFORCEMENT	320.30	1 PC	R 320.30	X
5 REAR BUMPER CLIPS	3.80	10 PCS	nc 38.00	✓
6 REAR BUMPER TOP PROTECTOR	410.00	1 PC	nc 410.00	✓
7 LH TAILLAMP (SPORT)	432.00	1 PC	Br 432.00	✓ 450.00
8 REAR LH FENDER 960.10	960.10	1 PC	Br 960.10	✓
9 REAR LH FENDER INNER SHIELD	65.40	1 PC	cm 65.40	✓
10 REAR LH FENDER INNER SHIELD CLIPS	3.80	8 PCS	nc 30.40	✓
11 REAR LH FENDER AIR SCROP GRILLE	60.30	1 PC	nc 60.30	✓
12 REAR LH FENDER GLASS MOULDING	380.60	1 PC	Sn 380.60	X
13 REAR LH FENDER INNER GARNISH	208.50	1 PC	nc 208.50	✓
14 REAR LH FENDER INNER FRONT RUBBER	64.30	1 PC	cm 64.30	✓
15 REAR LH FENDER INNER FRONT RUBBER CLIPS	3.80	4 PCS	nc 15.20	✓
16 REAR LH DOOR 801.70	801.70	1 PC	Br 801.70	✓
17 REAR LH DOOR FRAME STICKER	51.30	1 PC	nc 51.30	✓
18 REAR LH DOOR INNER RUBBER	160.30	1 PC	Sn 160.30	X
19 REAR LH DOOR LOWER PROTECTOR	192.80	1 PC	nc 192.80	✓
20 LH SIDE SKIRT	54.00	1 PC	cm 54.00	✓
21 LH SIDE SKIRT LH END GARNISH MUD FLAP	25.00	1 PC	nc 25.00	✓
22 LH SIDE SKIRT CLIPS	3.80	8 PCS	nc 30.40	✓
23 REAR TAILGATE 1072.80	1,072.80	1 PC	Br 1,072.80	✓
24 TAILGATE EMBLEM (SUBARU AWD)	72.30	1 PC	nc 72.30	✓
25 TAILGATE EMBLEM (FORESTER XT)	72.30	1 PC	nc 72.30	✓
26 REAR WINDSCREEN GLASS MOULDING	65.20	1 PC	nc 65.20	✓
27 REAR EXHAUST PIPE LH 668	668.00	1 PC	Br 668.00	✓
28 CENTRE EXHAUST PIPE 880	880.00	1 PC	Br 880.00	✓

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
 GST:201001158E RCB NO:201001158E

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY
 #07-16 AIG BUILDING
 SINGAPORE 079120

TEL: 64193000

FAX: 64153727

ATTN: Motor Claim Department

Estimate No: ES2190568/YISHUN

Date: 21 Jun 2021

Policy No: D21MTPV01005540

Veh Reg No: SMR6423A

Make/Model: SUBARU SUBARU
 FORESTER 2.0XT CVT
 AWD SR

WS Ref: TP/AIG

Claim Type: Third Party

Accident Date: 20/06/2021

TP Veh Reg No: SDU7338Y

Chassis No: JF1SJGK85JG099602

Engine No: FA20CB16035

Reg. Date: 25/10/2017

Estimate Repair Cost to Vehicle No :SMR6423A

Description	U/Price	Quantity	List Price	Amount
			S\$	S\$
29 REAR EXHAUST PIPE TOP HEAT COVER	85.00	1 PC	85.00	✓
30 REAR PANEL	320.80	1 PC	320.80	✓
31 LH TAILLAMP PANEL	90.50	1 PC	90.50	✓
32 REAR LH SHOCK ABSORBER B20365-SG200	720.00	1 PC	720.00	✓
33 REAR LH DRIVE SHAFT S28421-SG020	780.00	1 PC	780.00	✓
34 REAR LH KNUCKLE ARM	270.00	1 PC	270.00	✓
35 REAR LH KNUCKLE ARM BEARING	202.60	1 PC	202.60	✓
36 REAR LH CONTROL ARM (FOR ALIGNMENT)	228.00	1 PC	228.00	✓
37 REAR LH LOWER ARM	156.00	1 PC	156.00	✓
38 REAR LH TRAILING ARM	200.10	1 PC	200.10	✓
39 REAR CROSS MEMBER B20152-SG011	760.20	1 PC	760.20	✓
40 REAR CROSS MEMBER LH BRACKET	210.00	1 PC	210.00	✓
41 REAR LH UPPER ARM S20252-SG010	480.20	1 PC	480.20	✓
42 REAR LH ABS WIRE SENSOR	280.00	1 PC	280.00	✓
43 REAR LH HAND BRAKE CABLE	65.00	1 PC	65.00	✓
			12,626.50	
	Less 20%		2,525.30	10,101.20

Special Net

44 REAR LH FENDER GLASS GUM	30.00	1 PC	30.00	✓
45 REAR WINDSCREEN GLASS GUM	40.00	1 PC	40.00	✓
46 REAR LH TYRE	350.00	1 PC	350.00	808.00 280.00
47 REAR AXLE OIL (3 LTRS)	60.00	1 UNIT	60.00	✓
48 SPORT RIMS B1/CM	2,200.00	1 SET	2,200.00	✓
			2,680.00	2,680.00

Labour

49 TOWING (4 WHEEL TOWING) (Bill Attach)	100.00	1 LA	100.00	✓
50 REMOVE AND REFIX REAR WINDSCREEN GLASS	120.00	1 LA	120.00	✓
51 REMOVE & REFIX LH FENDER GLASS	100.00	1 LA	100.00	60.00

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
 GST:201001158E RCB NO:201001158E

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
 78 SHENTON WAY
 #07-16 AIG BUILDING
 SINGAPORE 079120
 TEL: 64193000 FAX: 64153727
 ATTN: Motor Claim Department

Estimate No: ES2190568/YISHUN
 Date: 21 Jun 2021
 Policy No: D21MTPV01005540
 Veh Reg No: SMR6423A
 Make/Model: SUBARU SUBARU
 FORESTER 2.0XT CVT
 AWD SR
 Chassis No: JF1SJGK85JG099602
 Engine No: FA20CB16035
 Reg. Date: 25/10/2017

WS Ref: TP/AIG
 Claim Type: Third Party
 Accident Date: 20/06/2021
 TP Veh Reg No: SDU7338Y

Estimate Repair Cost to Vehicle No :SMR6423A

Description	U/Price	Quantity	List Price	Amount
			<u>S\$</u>	<u>S\$</u>
52 REMOVE & REFIX SEAT,CARPET,GARNISH, TOP ROOF LINING,ETC	120.00	1 LA	120.00 ✓	
53 REMOVE & REFIX REAR LH UNDER CARRIAGE,DRIVE SHAFT,REAR AXLE ASSY,ETC	280.00	1 LA	280.00 2401	
54 REMOVE & REFIX EXHAUST ASSY & CHECK SYSTEM	100.00	1 LA	100.00 801	
55 REMOVE & REFIX REAR BUMPER ASSY,TAILLAMPS,REAR LH DOOR & ATTACHMENT,TAILGATE ASSY,CUT,WELD & RENEW REAR LH FENDER,LH TAILLAMP PANEL,REAR PANEL,KNOCK & REPAIR REAR LH FENDER INNER PANEL,REAR LH CHASSIS,LH ROCKER PANEL & REALIGN THE SAME	2,000.00	1 LA	2,000.00 17001	
56 REMOVE & REFIX REAR LH DOOR GLASS & CHECK CENTRAL LOCKING & POWER MIRROR	60.00	1 LA	60.00 ✓	
57 PUTTY & RESPRAY ON REAR LH DOOR,LH ROCKER PANEL,REAR LH FENDER,REAR LH WHEEL HOUSING & CHASSIS,TAILGATE,REAR BUMPER,REAR PANEL & ALL AFFECTED AREAS	1,600.00	1 LA	1,600.00 14001	
58 TO CONDUCT COMPUTERIZED WHEEL ALIGNMENT	80.00	1 PC	80.00 601	
59 RUSTPROOFING	120.00	1 LA	120.00 ✓	
			4,680.00	4,680.00

Total S\$ 17,461.20

Add GST @ 7% 1,222.28

Total Amount Payable S\$ 18,683.48

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

SMR 6423A

SUPP 1

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120
TEL: 64193000 FAX: 64153727
ATTN: Motor Claim Department

Estimate No: ES2190568/YISHUN
Date: 01 Jul 2021
Policy No: D21MTPV01005540
Veh Reg No: SMR6423A
Make/Model: SUBARU SUBARU
FORESTER 2.0XT CVT
AWD SR
Chassis No: JF1SJGK85JG099602
Engine No: FA20CB16035
Reg. Date: 25/10/2017

WS Ref: TP/AIG
Claim Type: Third Party
Accident Date: 20/06/2021
TP Veh Reg No: SDU7338Y

Estimate Repair Cost to Vehicle No :SMR6423A

Description	U/Price	Quantity	List Price	Amount
			<u>S\$</u>	<u>S\$</u>
Supplementary 1				
List Price				
1 REAR CROSS MEMBER LH BRACKET	127.00	1 PC	127.00	✓
			127.00	
		Less 20%	25.40	101.60
Special Net				
2 AXLE OIL (1 LTR)	120.00	1 PC	120.00	50wa 60sn
			120.00	120.00
			Total	S\$ 221.60
			GST Amount	S\$ 15.51
			Total Amount Payable	S\$ 237.11

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE