INTERNATIONAL FORMULA CENTER
176 Sin Ming Drive
Singapore 575721
Tel:64517737   Fax: 64517757

Estimate: IN S/0001/IFC

Attention : Claim Department

Customer		Date	22.06.2021
Name	AXA Insurance Pte Ltd	Vehicle Mod	BMW 428 IA
Address	8, Shenton Way, #27-01, AXA Tower	Vehicle No.	SDS 8886 K
	Singapore 068811	Job Card No	1
Phone	68804888/Fax No: 63382522		

Qty	Description	Unit Price	TOTAL	
	SDS 8886 K BMW 428IA Gran Coupe WBA4A52020GA69269			
	Parts			
1	Rear right door (List Price)	$1,369.60	B1 $1,369.60	✓
10	Rear right door panel clip (List Price)	$7.49	m $74.90	
1	Rear right window gear regulator (List Price)	$374.50	R $374.50	
	Totals 1 :		**$1,819.00**	
			5$	
	Labour			
1	Labour to remove damage door & to install new door.	$120.00	$120.00	6d
1	Labour to remove damaged door mechanism, window glass, door weather stripe, run channel, door lock, door knob, door handle onto new door & resetting power window.	$400.00	$400.00	25d
1	Labour to knock front right door & center pillar.	$300.00	nn $300.00	X
1	Paint spraying rear right door inside & outside & front right door.	$800.00	$800.00	600L
1	To check rear right door electrical & mechanism functionality.	$150.00	$150.00	3d

Not Authorised
Rehony B Gpaing
$ 2312·28

Payment Details

◉ Insurance Claim
○
○

LKK Auto Consultants hence notify the Repairer of the following:
• To resurvey before/after spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

	Total	**$5,408.00**

Acknowledged by Repairer
Signature:
Date:

Authorised Signature

Tan Hock Chuan