

PLEASE ARRANGE TO SURVEY VEHICLE AT
NO.8 KAKI BUKIT AVE 4
#03-21 S415875

6953111g
STK AUTO(S) PTE LTD

Email: stkautosg@gmail.com

Contact Person: TAN GUOHUA

HP: 91237949 / 63860669

Date: 22/06/2021
To: AXA INSURANCE PTE LTD
Attn: Motor Claim Department

TPAXA

Cecilie

ESTIMATED REPAIR COST DETAILS

Owner: LOH KAI YEONG
Vehicle Number: SNA 8383 X
Make & Model: TOYOTA CAMRY
Accident Date: 22/06/2021

MROS3AK5004011331

C/N	LIST ITEM	QTY	AMOUNT S\$
1	Rear boot lid <i>Repair Buckled</i>	1	944.35 ✓
2	Rear boot lid lock mechanism <i>2 Dented</i>	1	571.75 290
3	Rear boot lid lock striker <i>3 Dented</i>	1	121.11 ✓
4	Rear boot lid rubber stopper @ \$43.75 <i>all m</i>	2	87.5 ✓
5	Rear boot lid emblem <i>New</i>	1	61.1 ✓
6	Rear boot lid chrome stripe <i>New</i>	1	271.84 ✓
7	Rear boot lid reflector <i>New</i>	1	289.94 ✓
8	Rear boot lid reflector sealant <i>New</i>	1	50 ✓
9	Rear boot lid hinges @ \$171.45 <i>New</i>	2	342.9 ✓
10	Rear boot lid weather stripe <i>lt</i>	1	271.78 ✓
11	Rear bumper fascia <i>Distorted</i>	1	781.9 589
12	Rear bumper side retainer @ \$124.45 <i>New</i>	2	248.9 ✓
13	Rear bumper clips (1 set) <i>New</i>	1	129 30
14	Rear bumper sponge <i>New</i>	1	182.25 ✓
15	Rear bumper LH reflector <i>crushed</i>	1	171.7 85
16	Rear bumper attachment bracket @ \$182.25 <i>New</i>	2	364.5 ✓
17	Rear bumper beam <i>Dented</i>	1	371.85 ✓
18	LH tail lamp assy <i>lt</i>	1	371.78 ✓
19	Tail lamp sealant <i>New</i>	1	50 ✓
20	Rear end panel <i>Dented</i>	1	781.9 615
21	End panel trim board <i>Dented</i>	1	561.6 295
22	Trim board clips @ \$12.90 <i>New</i>	5	64.5 ✓
23	Rear LH fender <i>Repair</i>	1	1217.85 ✓
24	Rear windscreen glass moulding <i>2 New</i>	1	171.85 ✓
25	Rear windscreen clips @ \$12.90 <i>New</i>	14	180.6 ✓
			8662.36
Less 25% Disc			2165.59
Total			6496.77

A173.76

less 25%: 3130.32

3500

PLEASE ARRANGE TO SURVEY VEHICLE AT
NO.8 KAKI BUKIT AVE 4
#03-21 S415875

STK AUTO(S) PTE LTD
Email: stkautosg@gmail.com

Contact Person: TAN GUOHUA

HP: 91237949 / 63860669

Date: 22/06/2021
To: AXA INSURANCE PTE LTD
Attn: Motor Claim Department

ESTIMATED REPAIR COST DETAILS

Owner: LOH KAI YEONG
Vehicle Number: SNA 8383 X
Make & Model: TOYOTA CAMRY
Accident Date: 22/06/2021

C/N	NETT ITEM	QTY	AMOUNT S\$
1	Rear windscreen inner seal <i>Not m</i>	1	120 <i>x</i> .
		Less 10% Disc	12
		Total	108

SPECIAL NETT ITEM

1	Rear number plate <i>Not m</i>	1	50 <i>x</i>
2	Rear number plate casing <i>Not m</i>	1	50 <i>x</i> ,
3	Rear bumper reverse sensor <i>Damaged</i>	1	380 300
4	Rear windscreen sealant <i>Not m</i>	1	60 <i>x</i>
		Total	540

LABOUR COST

1	To remove & refix rear windscreen clips. <i>Not m</i>	180 <i>x</i> .
2	To remove & refix interior upholstery.	180 60
3	To remove & refix fuel tank.	250 <i>x</i> .
4	To remove & refix damaged parts, cuts & weld rear fender, end panel, straighten spare tyre panel and align all parts.	1200 800
5	To respray painting affected areas & conduct water proofing test.	1200 800
6	To tuff kote affected areas.	180 60
7	To check wiring systems.	80 30
	Total	3270

Total 10414.77
GST 7% 729.03
Grand Total 11143.8

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian Lij
L/S 23/06/21
06 Days

total: 5180.32
L/S: A.IK