LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PRE-REPAIR INSPECTION REPORT

SMRT AUTOMOTIVE SERVICES PTE LTD
60 WOODLANDS INDUSTRIAL PARK
E4SINGAPORE 757705

Ref: CS3/SMR21007103/Euf3e2
Date: 12/07/2021
Code: SMR

1. Policy Particulars :- (THIRD PARTY CLAIM)

	Insured Veh.	SHC 4559T	**Veh. Inspected**	SJR 4474B
	Policy No.		**Coverage ($)**	0.00
	Claim No.	TAX/06/21/2054	**Excess ($)**	0.00
	Assign From	HUA YEN	**Assign Date**	28/06/2021

2. Vehicle Particulars & Condition

	Make & Model	MITSUBISHI LANCER	**c.c**	1499
	Engine No.	HIDDEN	**Year of Reg.**	2009
	Chassis No.	JMYSRCY2A9U004318	**Colour**	SILVER
	Odometer	158195 KM	**Steering**	IN ORDER
	Brakes	IN ORDER	**Modification**	SPORTS RIM
	General	FAIR		

3. Conditions of Tyres

		Size	**Make**	**Balance**
	R/H Front Tyre	195/55 R15	BRIDGESTONE	4 mm
	L/H Front Tyre	195/55 R15	BRIDGESTONE	4 mm
	R/H Rear Tyre	195/55 R15	BRIDGESTONE	4 mm
	L/H Rear Tyre	195/55 R15	BRIDGESTONE	4 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.



5. General Information

	Accident Date	24/06/2021	**Inspect Date / Time**	29/06/2021 (01:00 PM)
	Survey held at	ALPHA PERFORMANCE SINGAPORE PTE LTD 48 TOH GUAN ROAD EAST #04-126,ENTERPRISE HUB,SINGAPORE 608586		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.
D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF $1,000-$2,000

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **4 Working Days**

Report Ref No. CS3/SMR21007103/Euf3e2

Inspected By

CHEN TSUE YEE
Automotive Assessor

K.K.LAU CPT(RET)
BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE
REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.