

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC5682M*Not Authorised***AAD2106-***Resumy B4 paint**819993.68*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

28 JUN 2021**SHC5682M**

JTDKB3FU103093690

TOYOTA

PRIUS GEN 4

24/06/2021

AIG.

29/01/2021

	PART
1	COVER, FRONT BUMPER
1	UNIT ASSY, HEADLAMP, LH
1	COMPUTER SUB-ASSY, HEADLAMP, LH NO.1
1	FENDER SUB-ASSY, FRONT LH
1	LINER, FRONT FENDER, LH
1	EMBLEM, SIDE PANEL
1	PANEL SUB-ASSY, FRONT DOOR, LH
1	WEATHERSTRIP, FRONT DOOR, LH
1	HINGE ASSY, FRONT DOOR, LOWER LH
1	HINGE ASSY, FRONT DOOR, UPPER LH
1	TAPE, BLACK OUT, NO.1 FRT LH
1	TAPE, BLACK OUT, NO.2 FRT LH
1	TAPE, BLACK OUT, NO.3 FRT LH
1	MOTOR ASSY, POWER WINDOW REGULATOR, FRT LH
1	REGULATOR SUB-ASSY, FRONT DOOR WINDOW, LH
1	FRAME SUB-ASSY, FRONT DOOR OUTSIDE HANDLE, LH
1	HANDLE ASSY, FRONT DOOR OUTSIDE, LH
1	PANEL SUB-ASSY, REAR DOOR, LH
1	WEATHERSTRIP, REAR DOOR OPENING TRIM, LH
1	HINGE ASSY, REAR DOOR, LOWER LH
1	HINGE ASSY, REAR DOOR, UPPER LH
1	TAPE, BLACK OUT, NO.1 REAR LH
1	TAPE, BLACK OUT, NO.2 REAR LH
1	TAPE, BLACK OUT, NO.3 REAR LH
1	MOTOR ASSY, POWER WINDOW REGULATOR, LH
1	REGULATOR SUB-ASSY, REAR DOOR WINDOW, LH

	LIST
\$	<i>ng</i> 521.00 ☒
\$	<i>Sm</i> 2,637.60 ☒
\$	<i>Sm</i> 3,772.50 ☒
\$	<i>B</i> 977.80 ☒
\$	<i>Dir</i> 210.30 ☒
\$	<i>ne</i> 54.60 ☒
\$	<i>B</i> 1,300.70 ☒
\$	<i>Sm</i> 231.30 ☒
\$	<i>B</i> 110.60 ☒
\$	<i>B</i> 97.50 ☒
\$	<i>ne</i> 13.30 ☒
\$	<i>ne</i> 43.50 ☒
\$	<i>ne</i> 26.30 ☒
\$	<i>TH</i> 926.00 ☒
\$	<i>B</i> 238.30 ☒
\$	<i>Sm</i> 193.50 ☒
\$	<i>Sm</i> 390.60 ☒
\$	<i>B</i> 1,294.90 ☒
\$	<i>Sm</i> 293.00 ☒
\$	<i>R</i> 87.10 ☒
\$	<i>R</i> 98.90 ☒
\$	<i>ne</i> 21.90 ☒
\$	<i>ne</i> 34.90 ☒
\$	<i>ne</i> 15.40 ☒
\$	<i>R</i> 926.00 ☒
\$	<i>Sm</i> 206.70 ☒

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

AAD2106-**SHC5682M**

- 1 PANEL SUB-ASSY, QUARTER, LH
- 1 LINER, REAR WHEEL HOUSE, LH
- 1 MOULDING ASSY, BODY ROCKER PANEL, LH
- 1 PANEL SUB-ASSY, QUARTER, LH
- 1 LINER, REAR WHEEL HOUSE, LH
- 1 SHAFT ASSY, FRONT DRIVE, LH
- 1 KNUCKLE, STEERING, LH
- 1 ARM SUB-ASSY, FRONT SUSPENSION, LOWER NO.1 LH
- 1 ABSORBER ASSY, SHOCK, FRONT LH
- 1 HEADLINING ASSY, ROOF
- 1 AIR BAG ASSY, CURTAIN SHIELD, LH
- 1 SENSOR ASSY, SIDE AIR BAG, LH, NO.2
- 1 SENSOR, DOOR SIDE AIR BAG, LH
- 1 COMPUTER ASSY, AIR BAG
- 1 AIR BAG ASSY, FRONT SEAT, LH
- 1 BELT ASSY, REAR SEAT, OUTER CENTER
- 1 BELT ASSY, REAR SEAT 3 POINT TYPE, OUTER LH
- 1 BELT ASSY, REAR SEAT, INNER W/CENTER, LH
- 1 BELT ASSY, REAR SEAT INNER W/CENTER, RH
- 1 BELT ASSY, REAR SEAT 3 POINT TYPE, OUTER RH
- 1 BELT ASSY, FRONT SEAT INNER, RH
- 1 BELT ASSY, FRONT SEAT INNER, LH
- 1 BELT ASSY, FRONT SEAT OUTER, RH
- 1 BELT ASSY, FRONT SEAT OUTER, LH

\$	Bj	871.50	✓
\$	Sm	139.80	X
\$	Dis	594.80	✓
\$	Repeal	871.50	X
\$	Sm	139.80	X
\$	Bt	1,251.70	✓
\$	Bj	663.40	✓
\$	Dis	760.10	✓
\$	Bj	472.30	✓
\$	Tn	2,125.70	✓
\$	Burn	1,748.10	✓
\$	Me	709.30	✓
\$	Me	379.20	✓
\$	Me	1,546.00	✓
\$	Burn	1,008.80	✓
\$	Sm	628.10	X
\$	Tn	995.10	✓
\$	Sm	251.60	X
\$	Sm	251.60	X
\$	Tn	995.10	✓
\$	Sm	177.00	X
\$	Sm	177.00	X
\$	Tn	995.10	✓
\$	Tn	995.10	✓
TOTAL		\$ 26,540.80	
25%		\$ 6,635.20	
		\$ 19,905.60	

Special Nett

- 1 FRONT BUMPER SIDE CLIP
- 1SET FRONT BUMPER CLIP
- 1 TYRE
- 1 HUB CAP
- 1 RIM
- 2 FENDER CLIP

\$	Me	60.00	50% ✓
\$	va	85.00	X
\$	Sm	350.00	X
\$	cm	211.50	✓
\$	Sm	1,879.40	X
\$	Me	130.00	50% ✓

Trans-cab Auto Services Pte Ltd**AAD2106-**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC5682M

2 FENDER LINER CLIP	\$	nn 65.00	X
2SET DOOR TRIM CLIP	\$	nn 70.00	X
2SET DOOR WEATHERSTRIP CLIP	\$	nn 130.00	X
1 DOOR STICKER TRANSCAB	\$	nn 350.00	60sm
1 DOOR STICKER TEL NO.	\$	nn 1,879.40	60sm
1SET CLIP, ROCKER PANEL MOULDING	\$	nn 65.00	✓
TOTAL	\$	2,715.90	

TOTAL PARTS \$ 22,621.50**LABOUR**

To Rust-Proofing and apply undercoat Of The Affected Areas.	\$	240.00	12cl
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	380.00	12cl
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	1,600.00	100cl
To transfer of rear end panel fittings, attachment to facilitate bodywork repair.	\$	nn 380.00	X
Putty And Spray Painting Of The Affected Portion.	\$	1,600.00	154cl
To reinstall rear bumper parking sensor.	\$	nn 170.00	X
To transfer of tire, rim and on wheel balancing.	\$	170.00	2cl
To Check Electrical Lighting Concerned.	\$	170.00	3cl
To check steering geometry and computer wheel alignment	\$	220.00	6cl

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC5682M

AAD2106-

To remove and refit of rear fender fittings, attachment and \$ *nn* 170.00 *X***TOTAL** \$ **5,100.00****Over All Total** \$ **27,721.50****(PART-BY-PART) Repair Days** *20 days**10 days***LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC5682M

AAD2106-086

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

SHC5682M

JTDKB3FU103093690

TOYOTA

PRIUS GEN 4

24/06/2021

AIG

29/01/2021

PART

1 FRAME SUB-ASSY, FRONT DOOR, FRONT LOWER LH

		LIST	
	\$	Dir	144.60 ✓
TOTAL	\$		144.60
25%	\$		36.15
	\$		108.45

Vehicle Registration Number

SHC5682M

Is company?

Yes

Name Of Registered Owner

TRANS-CAB SERVICES PTE LTD

Company Reg No

20000087

Email Address

claims@transcab.com.sg

Mobile Phone No

(Phone) +65-62865665

Alternative Phone No

(Office) +65-62565666

Manufacturer

Toyota

Model

Prius

Exact purpose for which vehicle was being used at time of accident

Private Use

Are you claiming under your own insurance policy for repair to your vehicle?

No - Claiming third party

Vehicle Category

Taxi

Transmission

Auto

Color

130

Name of Insurance Company

AXA Insurance Pte Ltd

Type of Coverage

ThirdParty

Policy Policy

Yes

Policy Number

912413997

Claim Note Number

NA

Name of Driver

ANG POW TIAN

NRIC No

30000340