

EROFIA MOTOR TRADING PTE LTD

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 Fax : 67528669

Co. Reg No. 201202259N

Email: erofia@singnet.com.sg

AG

Owner : Muhammad Syaifulrizal Bin Saadon

Accident Date : 29-Apr-21

Vehicle No : FBL6844E

Vehicle Model : Yamaha Sniper T150

Estimated Repair Costs

Qty	Description List Items	Amount S(\$)
2	Front fork tube assy	\$ 640.00 ?
1	Fork under bracket	\$ 205.00 ?
1	Front wheel rim R	\$ 320.00 X
1	Front rim shaft 11	\$ 95.00 X
1	Front rim bearing 11	\$ 52.00 X
1	Front brake disc 11	\$ 185.00 X
1	Meter assy C47	\$ 625.00 ✓
1	Headlamp	\$ 280.00 ?
1	Mirror (1 set) B20	\$ 180.00 ✓
1	Handle-bar	\$ 102.00 ?
1	Handle-bar end (1 set) 115 C47	\$ 95.00 ✓
1	Handle front cover C47	\$ 105.00 ✓
1	Handle rear cover 11	\$ 85.00 X
1	Front horn inner cover centre black	\$ 78.00 ?
1	Front signals 11	\$ 150.00 X
1	Brake lever C47	\$ 65.00 ✓
1	Fairing assy (1 set) C47	\$ 560.00 ✓
1	Front side lower cover D.S	\$ 160.00 ✓
1	Front footrest bracket (1 set) Bent	\$ 98.00 ✓
1	Brake pedal Bent	\$ 65.00 ✓
1	Gear pedal Bent	\$ 58.00 ✓
1	Rear footrest - (1 set) 11	\$ 88.00 X
1	Rear footrest bracket 11	\$ 98.00 X
1	Exhaust assy 11	\$ 520.00 X
1	Exhaust protector - Front 11	\$ 52.00 X
1	Exhaust protector - rear SCN N/C	\$ 72.00 X
1	Exhaust pipe end cover SCN N/C	\$ 65.00 X
1	Rear fender bracket Bent	\$ 78.00 ✓
1	Rear rim shaft C47	\$ 98.00 ✓
		\$ 5,274.00
		\$ 527.40
		\$ 4,746.60

Not Authorized

Less 10%

2/5/21

5-7/21

2/5/21

4 days

When the other up

EROFIA MOTOR TRADING PTE LTD

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 Fax : 67528669

Co. Reg No. 201202259N

Email: erofia@singnet.com.sg

Owner : Muhammad Syaifulrizal Bin
Saadon

Accident Date : 29-Apr-21

Vehicle No : FBL6844E

Vehicle Model : Yamaha Sniper
T150

Estimated Repair Costs

Special Net Items

1	Number plate (1 set)	<i>for sun</i>	\$	38.00	<i>10</i>
2	Fork oils		\$	30.00	<i>7</i>
2	Fork oil seals		\$	56.00	<i>7</i>
1	Steering cone (1 set)		\$	98.00	<i>7</i>
1	Rear box	<i>cur/dyed</i>	\$	520.00	<i>400</i>
1	Rear ox braxket	<i>surf</i>	\$	180.00	<i>✓</i>
1	E.R.P IU	<i>Dyed</i>	\$	180.00	
1	Sticker (1 set)	<i>all</i>	\$	120.00	<i>✓</i>
			\$	1,222.00	

S/No. Labour

1	To provide towing service (LOD)	\$	50.00	30
2	To check wiring and reset headlamp focusing	\$	17 80.00	X
3	To provide labour	\$	480.00	300
4	To repair body frame	\$	350.00	?
		\$	960.00	

Grand Total

\$ 6,928.60

Singapore Dollars: Six Thousand Nine Hundred Twenty-Eight and Cents: Sixty only

EROFIA MOTOR TRADING PTE LTD

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Page 2 of 16
Signature:
Date: