ASS. REC. BY: Steve T REF: CS/091210737979/EVF3

ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured: SDY 9282P

Policy No.

Claims No. M11D3312107

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S
	X

Bal. or Market Value:

IDAC Accident Rport: Consistent? : Yes or No

SIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Sum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SGP 179J Yr Regn: 29/3/29

Type: M.Car / M.Cycle / Bus / Van / Lorry / Texi / Prime Mover / Truck / Trailer or

Make: Volkswagen Touran c.c 1395

Colour Beige A/C: Insured / Std / Nil / N

Sp.Reading 71846 T/Radio: Insured / Std / Nil / N

Eng/No:

C/No: WV6ZZZ1T2KW072718

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 215/55R17

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or B Pirelli

Front		Rear	
R/Bal.	5 mm	R/Bal.	5 mm
U/Bal.	5 mm	U/Bal.	5 mm
D.O.A.	3/7/21	D.O.I.	8/7/21

Survey held at Volkswagen 8/7/21

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or Re RH

The U/C / Chassis frame / Body Structure affected due to collisio

Date / Time	Action / Instruction
	LAW - 149K
27/7/21	Final fig $3681.31 confirmed by email (Red 6188.16.62%)

Date/Time, File,Poss lo?: ☐ : Proll. Report

☐ : Final Report

Date/Time, File Return lo?

28/7/21-Typist

Days Of Repair: 4

Resurvey No. of Trip: 1

Add Fee: ☐ : Site Insp ($)

☐ : Interview ($)

☐ : Tech. Inve (%)

☐ : Weal and ($)

Survey Fee:	250
Transportation:	60
S + RS + SI	80
Photos	37
Others	
TOTAL	427

Assessor Name : TP

Insp Sum / U.P.I: Rs $3681.31