

TP III
Jasper.

SMN1594T. 2019 July.

76121 Ag

Honda Vezel 1496 cc

RU11311794

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Rear Number Plate	} NP per	30(SN) X
Rear Number Plate Holder		30(SN) X
Rear Bumper	Deformed	745.30
Rear Bumper Clips	new	30(SN)
Rear Bumper Side Holder x 02	new	33 X 2 = 66
Rear Bumper Reflector x 02	new	151 X 2 = 302
Reverse Sensor	Dented	280(SN) 200(SN)
Rear End Panel	Dented	474.10
Rear End Panel Top Garnish	Deformed	188
Rear End Panel Sealant	new	60(SN)
Rear End Panel Antenna Sensor	NP	85.50 X
Rear End Panel Buzzer	NP	85.20 X
Taillamp x 02	new	462.6 X 2 = 925.20
Taillamp lower Garnish x 02	Deformed	195 X 2 = 390

SMN1594T.

Tailgate	Distorted	1100.40 ✓
Tailgate Lock	Dmg	185.40 ✓
Tailgate Weatherstripe	wt	189 ✓
Tailgate Inner Trim Board	replaced	285.50 ✓
Tailgate Inner Trim Board Clips	nr	30(SN) ✓
Tailgate Reflector x 02	wt	364.60 x 2 = 729.20 ✓
Tailgate Glass Moulding	2	112.20 ✓
Tailgate Glass Sealant	nr	60(SN) ✓
Honda Logo	1 H nr	38.40 X
Vezel Wording	nr	48.50 ✓
Rear Fender Inner Trim Board x 02	2	325.4 x 2 = 650.80 +
Rear Fender Inner Trim Board Clips	nr	60(SN) X
Rear Fender Inner Shield x 02		198.1 x 2 = 396.20 +
Rear Fender Inner Shield Clips	nr	40(SN) X
Rear Fender Arc Protector x 02		184.7 x 2 = 369.40 +
Rear Fender Arc Protector Clips		40(SN) X

SMN1594T.

Spare Tyre Panel Top Cover	del	306.60	✓
Spare Tyre Panel Undercover	torn	254.90	✓
Spare Tyre Panel Undercover Clips	new	30(SN)	✓
Rear Exhaust Pipe.	Repair	785	+
Rear Exhaust Mounting.	2 HP	35.40	+
Rear Exhaust Heat Shield.	new	155.40	+
Tool Box Sponge	ould	285.	✓
	S.N: 410		
	6587.70		
	5270.16		

total: 7730.16 H/S: 6.6K. 06 Days (6100)	Panel Beating	1400	800
	Spray Painting	1200	800
	Wiring.	50	30
	To remove reverse sensor	100	50
	To remove rear camera.	100	50
	To spray tuff coat.	150	60
	To remove upholstery.	150	60
	To transfer tailgate fittings	150	80
	To remove tailgate g/s	180	120
	To remove rear exhaust pipe.	150	X.