趙 源 摩 哆
Chew Goon Motor

Blk 10, Ang Mo Kio Industrial Park 2A, Avenue 5
#01-15, 16, 17 & #03-05, AMK Autopoint Singapore 568047
Tel: 6484 1626 (24Hrs)   Fax: 6484 0465
Business Reg. No: 221880/00C   GST Reg. No: MX-0486007-AO

Not Authorn
l/ship $1300/. Max
Ready After Paint
3days

To: __AIG Asia Pacific Insurance Pte Ltd__

Policy No: _____ Third Party

Date: __26.07.2021__

Accident Date : 21.07.2021

Specialised in Car Painting, Welding,
Panel-Beating and Insurance Claim.

ESTIMATE

承接汽车烧焊喷漆及
代理各种车辆赔偿

Estimate Cost Of Repair To "Hyundai Elantra" Reg. No. SKG4549R
Claiming Against Your Insured Reg. No. SLH2346E

数 量 Quantity	货 名 DESCRIPTION	单价 Unit Price	银 Amount 额 $ cts.
1pc	Front Bumper *474.60*		521.00
10pcs	Front Bumper Clips	3.00	30.00
1pc	Front Bumper Top Retainer LH		13.00 X
1pc	Front Bumper Sponge		121.00 X
1pc	Front Bumper Reinforcement		550.00 X
1pc	Front Bumper Bracket LH		25.00 X
1pc	Front Bumper Fog Lamp LH		267.70
1pc	Front Bumper Corner Retainer LH *1482.30*		25.00 X
1pc	Headlamp LH		1,822.00
1pc	Headlamp Lower Panel LH (Fiber)		980.00 X
			4,354.70
	Less 20%		870.94
			3,483.76
	To Conduct Electrical Check, Focus Headlamp		30.00 *2cl*
	To Remove / Refit, Radiator System, Bleed, Refill Coolant To Facilitate Repair.		80.00 X
	To Remove / Refit Air Con Condenser & Refill Air Con Gas To Facilitate Repair.		120.00 X
	Labour Charge - Panel Beating, Front N/S Fender and Parts Replacement		400.00 *25cl*
	To Respray Affected Areas		550.00 *400l*
	Total :		4,663.76