LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PRE-REPAIR INSPECTION REPORT

AXA INSURANCE PTE LTD

8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811

ATTN : YU DOMINIC YISHAN

Ref: CS3/ASM21002516/T1tf3e2

Date: 16/03/2021

Code: ASM

1. Policy Particulars :- (THIRD PARTY CLAIM)

	Insured Veh.	SHC 3316J	**Veh. Inspected**	SMX 4963P
	Policy No.	VFX/P2419138	**Coverage ($)**	0.00
	Claim No.	S1M035A1	**Excess ($)**	0.00
	Assign From	YU DOMINIC YISHAN	**Assign Date**	23/02/2021

2. Vehicle Particulars & Condition

	Make & Model	HONDA SHUTTLE	**c.c**	1496
	Engine No.	HIDDEN	**Year of Reg.**	2021
	Chassis No.	GK82100361	**Colour**	BLACK
	Odometer	3235 KM	**Steering**	IN ORDER
	Brakes	IN ORDER	**Modification**	SPORTS RIM
	General	GOOD		

3. Conditions of Tyres

		Size	**Make**	**Balance**
	R/H Front Tyre	185/60 R15	YOKOHAMA	6 mm
	L/H Front Tyre	185/60 R15	YOKOHAMA	6 mm
	R/H Rear Tyre	185/60 R15	YOKOHAMA	6 mm
	L/H Rear Tyre	185/60 R15	YOKOHAMA	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.



5. General Information

	Accident Date	19/02/2021	**Inspect Date / Time**	24/02/2021 (11:53 AM)
	Survey held at	KY AUTO PTE LTD 25 KAKI BUKIT ROAD 4 #05-23 SYNERGY @ KB SINGAPORE 417800		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.
D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF $5,000-$6,000

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **8 Working Days**

Report Ref No. CS3/ASM21002516/T1tf3e2

Inspected By

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.