CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240

Movement that inspires

Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name	LCV00443/SONIYA HITEN KAMDAR
	Reg No/Reg Date	SMY825B / 15/02/202
	Date In/Mileage	/ 0
	Chassis No	KNARH81BVM5047714
	Engine No	D4HELH251848
	Make/Model	KIA/SORENTO 2.2 A D SX SR G703
	Colour/Trim	B4U GRAVITY BLUE / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
LAX00000	Credit	11/08/2021/ 09:35	BLC	442 / CocoLu	37660

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
E PNT88000 1 1 2 2 RENEW FRT BUMPER, BONNET, FRT SUPPORT PANEL, FRT FENDER RH& LH 5.5 x 400 REPAIR FRT DOOR RH & LH				2400.00 2200
E PNT88000 REMOVE & INSTALL AIRCON CONDENSOR & RADIATOR				100.00
M SUNDRY TOP UP AIRCON GAS				80.00
M SUNDRY FRT NUMBER PLATE WITH FRAME				50.00
M SUNDRY APPLY SEALANT FOR ACCIDENT PORTION				40.00
E PNT98000 1 1 2 SPRAY PAINT FOR FRT BUMPER, BONNET, FRT FENDER RH & LH, FRT SUPPORT 6 x 350 FRT DOOR RH & LH 2				3040.00 2100
A 90000001 CHECK WIRING & ELECTRICAL SYSTEM				30.00
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM				120.00
A 90000001 RENEW FRT DASHBOARD				400.00
A 90000001 RENEW FRT AIRBAG AND SEAT BELTS				400.00
A 90000001 REMOVE & INSTALL FRT RIGHT & LEFT SEATS AND SEAT AIRBAG				400.00
A 90000001 REMOVE & INSTALL ROOFLINING				200 400.00
E PNT88000 RENEW FRT WINDSCREEN				240.00
M SUNDRY APPLY SEALANT FOR FRT WINDSCREEN				80.00
M SUNDRY TRANSFER FRT RIGHT RIM				30.00
M SUNDRY				220.00

Estimate

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Scanned with CamScanner

CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240

Movement that inspires

Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name	LCV00443/SONIYA HITEN KAMDAR
	Reg No/Reg Date	SMY825B / 15/02/202
	Date In/Mileage	/ 0
	Chassis No	KNARH81BVM5047714
	Engine No	D4HELH251848
	Make/Model	KIA/SORENTO 2.2 A D SX SR G703
	Colour/Trim	B4U GRAVITY BLUE / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
LAX00000	Credit	11/08/2021/ 09:35	BLC	442 / CocoLu	37660

	Description of Goods / Services	Qty	Unit Price	Disc%	Amount
	APPLY SOLAR FILM FOR FRT WINDSCREEN				
M	SUNDRY				30 50.00
	Sundry				
M	BRACKET, IU ADHESIVE / NEC	1.00	26.00	00.00	26.00
M	COVER-FR BUMPER UPR / BR	1.00	561.00	20.00	448.80
M	SKID PLATE-FR BUMPER / CUT	1.00	166.00	20.00	132.80
M	LIP-FR BUMPER ? / CUT	1.00	34.00	20.00	27.20
M	REINF ASSY-FR BUMPER,LH / BR	1.00	11.00	20.00	8.80
M	REINF ASSY-FR BUMPER,RH / BR	1.00	11.00	20.00	8.80
M	GRILLE-FRONT BUMPER / BR	1.00	246.00	20.00	196.80
M	PIECE-BUMPER GRILLE / BR	1.00	105.00	20.00	84.00
M	AIR DUCT-FR BUMPER,LH / BR	1.00	28.00	20.00	22.40
M	AIR DUCT-FR BUMPER,RH / BR	1.00	28.00	20.00	22.40
M	LAMP ASSY-FR FOG,RH / BR	1.00	646.00	20.00	516.80
M	LAMP ASSY-FR FOG,LH / BR	1.00	646.00	20.00	516.80
M	WIRING HARNESS-FR BUMPER / TN	1.00	213.00	20.00	170.40
M	ABSORBER-FRONT BUMPER ENERGY / BR	1.00	117.00	20.00	93.60
M	STIFFENER ASSY-FR BUMPER LWR / BR	1.00	102.00	20.00	81.60
M	BRACKET-FR BUMPER SIDE,LH / BR	1.00	15.00	20.00	12.00
M	BRACKET-FR BUMPER SIDE,RH / BR	1.00	15.00	20.00	12.00
M	GARNISH ASSY-RAD GRILLE,UPR / BR	1.00	209.00	20.00	167.20
M	COVER-RADIATOR GRILLE UPR / BR	1.00	107.00	20.00	85.60
M	GRILLE ASSY-RADIATOR / BR	1.00	692.00	20.00	553.60
M	MOULDING-FRT BPR LICENSE PLATE / BR	1.00	27.00	20.00	21.60
M	ULTRASONIC SENSOR ASSY-P.A.S / BR	2.00	189.00	20.00	302.40
M	ULTRASONIC SENSOR ASSY-P.A.S / BR	2.00	171.00	20.00	273.60
M	GUARD ASSY-FRONT WHEEL,LH / TN	1.00	76.00	20.00	60.80
M	GUARD ASSY-FRONT WHEEL,RH / CRU	1.00	76.00	20.00	60.80
M	PANEL ASSY-HOOD / DD	1.00	1438.00	20.00	1150.40
M	HINGE ASSY-HOOD,RH / BT	1.00	62.00	20.00	49.60
M	HINGE ASSY-HOOD,LH / BT	1.00	62.00	20.00	49.60
M	INSULATOR-FENDER RH ? XNN	1.00	31.00	20.00	24.80
M	INSULATOR-FENDER LH ? XNN	1.00	31.00	20.00	24.80

Estimate

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Scanned with CamScanner

CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240

Movement that inspires

Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name	LCV00443/SONIYA HITEN KAMDAR
	Reg No/Reg Date	SMY825B / 15/02/202
	Date In/Mileage	/ 0
	Chassis No	KNARH81BVM5047714
	Engine No	D4HELH251848
	Make/Model	KIA/SORENTO 2.2 A D SX SR G703
	Colour/Trim	B4U GRAVITY BLUE / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
LAX00000	Credit	11/08/2021/ 09:35	BLC	442 / CocoLu	37660

	Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M	INSULATOR-FENDER UPPER,RH ? X NN	1.00	17.00	20.00	13.60
M	INSULATOR-FENDER UPPER,LH ? X NN	1.00	17.00	20.00	13.60
M	PANEL ASSY-FENDER,RH / BR	1.00	702.00	20.00	561.60
M	PANEL ASSY-FENDER,LH / BR	1.00	702.00	20.00	561.60
M	BEAM COMPLETE-FR BUMPER / BR	1.00	674.00	20.00	539.20
M	CARRIER ASSY-FRONT END MODULE / BR	1.00	661.00	20.00	528.80
M	LIFTER-HOOD X ~~BR~~ NN	1.00	60.00	20.00	48.00
M	PAD-HOOD INSULATING / CRY	1.00	172.00	20.00	137.60
M	LATCH ASSY-HOOD / BT	1.00	105.00	20.00	84.00
M	TCU ? / ~~NEC~~ BR	1.00	1303.00	20.00	1042.40
M	LAMP ASSY-HEAD,RH / BR	1.00	2279.00	20.00	1823.20
M	LAMP ASSY-HEAD,LH / BR	1.00	2279.00	20.00	1823.20
M	PROTECTOR-WIRING ? X NN	1.00	17.00	20.00	13.60
M	PROTECTOR-WIRING ? X NN	1.00	20.00	20.00	16.00
M	BRACKET-WIRING MTG ? X NN	1.00	9.00	20.00	7.20
M	COVER ASSY-COWL TOP / CUT	1.00	316.00	20.00	252.80
M	GLASS-WINDSHIELD / BR	1.00	1536.00	20.00	1228.80
M	MOULDING-WINDSHIELD,UPR / NEC	1.00	21.00	20.00	16.80
M	BRACKET-W/S MLDG MTG,LH / NEC	1.00	35.00	20.00	28.00
M	BRACKET-W/S MLDG MTG,RH / NEC	1.00	35.00	20.00	28.00
M	GARNISH ASSY- RH / CUT	1.00	116.00	20.00	92.80
M	GARNISH ASSY- LH ? / NEC	1.00	116.00	20.00	92.80
M	CONDENSER ASSY-COOLER / BR	1.00	934.00	20.00	747.20
M	DAM-AIR / BR	1.00	23.00	20.00	18.40
M	GUARD-AIR,RH / BR	1.00	12.00	20.00	9.60
M	PIPE & TUBE ASSY ? X NN	1.00	785.00	20.00	628.00
M	RADIATOR ASSY / BR (photo)	1.00	814.00	20.00	651.20
M	INSULATOR-RADIATOR MTG,LWR ? X NN	1.00	10.00	20.00	8.00
M	BRACKET ASSY-RADIATOR MTG,UPR ? X NN	1.00	24.00	20.00	19.20
M	HOSE ASSY-RADIATOR,UPR ? X NN	1.00	48.00	20.00	38.40
M	HOSE ASSY-RADIATOR,LWR ? X NN	1.00	52.00	20.00	41.60
M	HOSE ? X NN	1.00	27.00	20.00	21.60
M	RESERVOIR & HOSE ASSY-RAD ? X NN	1.00	165.00	20.00	132.00

Estimate

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Scanned with CamScanner

CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240

Movement that inspires

Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name	LCV00443/SONIYA HITEN KAMDAR
	Reg No/Reg Date	SMY825B / 15/02/202
	Date In/Mileage	/ 0
	Chassis No	KNARH81BVM5047714
	Engine No	D4HELH251848
	Make/Model	KIA/SORENTO 2.2 A D SX SR G703
	Colour/Trim	B4U GRAVITY BLUE / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
LAX00000	Credit	11/08/2021/ 09:35	BLC	442 / CocoLu	37660

	Description of Goods / Services	Qty	Unit Price	Disc%		Amount
M	HOSE ASSY-WATER ? X MM	1.00	27.00	20.00		21.60
M	BLOWER ASSY ? / BR	1.00	698.00	20.00	/	558.40
M	GUARD-AIR ? / BR	1.00	64.00	20.00	/	51.20
M	SHIELD-AIR INTAKE X MM	1.00	27.00	20.00		21.60
M	DUCT ASSY-AIR ? / BR	1.00	45.00	20.00	/	36.00
M	DUCT ASSY-AIR ? / BR	1.00	69.00	20.00	/	55.20
M	CLEANER ASSY-AIR / BR	1.00	175.00	20.00	/	140.00
M	SENSOR ASSY-AIR FLOW ? X MM	1.00	276.00	20.00		220.80
M	HOSE ASSY-AIR INTAKE ? X MM	1.00	158.00	20.00		126.40
M	GUARD ASSY-AIR,LH ? / BR	1.00	49.00	20.00	/	39.20
M	INTERCOOLER / MM	1.00	943.00	20.00	/	754.40
M	HOSE-BYPASS ? X MM	1.00	68.00	20.00		54.40
M	VALVE-BYPASS ? / BT	1.00	~~797.00~~	20.00	139-	637.60
M	HOSE-INTERCOOLER INLET X MM	1.00	184.00	20.00		147.20
M	BRKT-I/C, UPR X MM	1.00	29.00	20.00		23.20
M	RESONATOR ? X MM	1.00	396.00	20.00		316.80
M	STARTER ASSY ? X MM	1.00	645.00	20.00		516.00
M	MANIFOLD ASSY-INTAKE ? X MM	1.00	760.00	20.00		608.00
M	ELECTRONIC CONTROL UNIT ~~Rec~~ / X	1.00	1906.00	20.00		1524.80
M	PANEL ASSY-UNDER COVER ? X MM (Front RH) CVT	1.00	339.00	20.00		271.20
M	WHEEL ASSY-ALUMINIUM /	1.00	799.00	20.00	/	639.20
M	CRASH PAD ASSY-MAIN / BR	1.00	865.00	20.00	/	692.00
M	HEADLINING ASSY / CRU	1.00	1536.00	20.00	/	1228.80
M	MAP BOARD ASSY-FRT SEAT BACK,R ? X MM	1.00	216.00	20.00		172.80
M	ADJUSTER ASSY-HEIGHT ? X MM	2.00	43.00	20.00		68.80
M	S/BELT ASSY-FR RH / Jemmed	1.00	471.00	20.00	/	376.80
M	S/BELT ASSY-FR LH / Jemmed	1.00	471.00	20.00	/	376.80
M	BUCKLE ASSY-FR S/BELT,RH ? X MM	1.00	97.00	20.00		77.60
M	BUCKLE ASSY-FR S/BELT,LH ? X MM	1.00	97.00	20.00		77.60
M	BUZZER ASSY-PIEZO / MIS	1.00	68.00	20.00	/	54.40
M	SENSOR ASSY-A TYPE CRASH / Rec	1.00	44.00	20.00	/	35.20
M	HORN ASSY-BURGLAR ALARM X ~~BR~~ MM	1.00	107.00	20.00		85.60
M	SENSOR ASSY-PRESS TYPE CRASH / Rec	1.00	88.00	20.00	/	70.40

Estimate

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Scanned with CamScanner

CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240

Movement that inspires

Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name	LCV00443/SONIYA HITEN KAMDAR
	Reg No/Reg Date	SMY825B / 15/02/202
	Date In/Mileage	/ 0
	Chassis No	KNARH81BVM5047714
	Engine No	D4HELH251848
	Make/Model	KIA/SORENTO 2.2 A D SX SR G703
	Colour/Trim	B4U GRAVITY BLUE / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
LAX00000	Credit	11/08/2021/ 09:35	BLC	442 / CocoLu	37660

	Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M	SENSOR ASSY-A TYPE CRASH — NEC	1.00	48.00	20.00	38.40
M	MODULE ASSY-STRG WHEEL AIR BAG — BR	1.00	1383.00	20.00	1106.40
M	AIR BAG ASSY-PASSENGER — BR	1.00	1278.00	20.00	1022.40
M	CURTAIN AIR BAG MODULE,RH ? X NN	1.00	1483.00	20.00	1186.40
M	CURTAIN AIR BAG MODULE,LH — BR	1.00	1483.00	20.00	1186.40
M	SWITCH ASSY-MULTIFUNCTION ? X NN	1.00	468.00	20.00	374.40

Estimate

Steve (LKK) 90- NM AL
11/8/21, 1.00pm
Excess - ?
P/P
My BL 50
15 days

LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Confirm & accepted by

	Nett	39,549.20
7% GST on	39549.20	2768.44
	Total Payable	42,317.64

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Scanned with CamScanner