

BIFROST AUTO PTE LTD

REPAIR ESTIMATE

DATE: 10-Aug-21

INSURANCE: FXA

MODEL: HYUNDAI I40

VEHICLE NO.: SHC 8703S

DESCRIPTION	QTY	LIST PRICE	AMOUNT
BONNET <i>key</i>	1	\$ 2,265.90	\$2,265.90
BONNET LOCK <i>HL</i>	1	\$ 142.40	\$142.40
RADIATOR GRILLE H EMBLEM <i>HL</i>	1	\$ 129.50	\$129.50
RADIATOR GRILLE <i>HL</i>	1	\$ 1,480.00	\$1,480.00
FRONT BUMPER COVER <i>mainly made 50% SH</i>	1	\$ 1,052.20	\$1,052.20
FRONT BUMPER GRILLE (RH) <i>HL</i>	1	\$ 149.20	\$149.20
FRONT BUMPER BRACKET TOP (RH) <i>HL</i>	1	\$ 44.80	\$44.80
FRONT BUMPER BRACKET (RH) <i>was cracked / broken</i>	1	\$ 49.20	\$49.20
FRONT BUMPER RETAINER MOUNTING RH <i>HL</i>	1	\$ 76.20	\$76.20
FRONT BUMPER GRILLE AIR DUCT (RH) <i>HL</i>	1	\$ 126.20	\$126.20
WIPER CONTAINER ASSY RH <i>HL</i>	1	\$ 281.60	\$281.60
HEADLAMP SUPPORT PANEL ASSY <i>broken</i>	1	\$ 907.40	\$907.40
HEADLAMP (RH) <i>mainly broken</i>	1	\$ 2,776.00	~~\$2,776.00~~
HEADLAMP SUPPORT TOP COVER <i>HL</i>	1	\$ 222.60	\$222.60
FRONT FENDER (RH) <i>Dented</i>	1	\$ 663.00	\$663.00
FRONT FENDER APRON PANEL (RH) <i>HL</i>	1	\$ 637.00	\$637.00
FRONT FENDER SHIELD (RH) <i>SH</i>	1	\$ 174.90	\$174.90
FRONT DOOR MIRROR SIDE GARNISH <i>HL</i>	1	\$ 225.00	\$225.00
FRONT DOOR BLACK PLASTIC COVER <i>HL</i>	1	\$ 84.20	\$84.20
FRONT DOOR MIRROR ASSY (RH) <i>HL</i>	1	\$ 893.50	\$893.50
FRONT DOOR (RH) <i>new key</i>	1	\$ 2,256.40	~~\$2,256.40~~
FRONT DOOR RUBBER <i>HL</i>	1	\$ 290.50	\$290.50
FRONT DOOR HINGE UPPER (RH) <i>HL</i>	1	\$ 113.60	\$113.60
FRONT DOOR HINGE LOWER (RH) <i>HL</i>	1	\$ 125.70	\$125.70
FRONT DOOR CHECK (RH) <i>HL</i>	1	\$ 91.80	\$91.80
FRONT WHEEL RIM (RH) <i>HL</i>	1	\$ 650.60	\$650.60
FRONT WHEEL HUB CAP (RH) <i>cut</i>	1	\$ 214.20	~~\$214.20~~
KNUCKLE ARM (RH) <i>HL</i>	1	\$ 1,104.00	\$1,104.00
FRONT WHEEL BEARING AND HUB (RH) <i>HL</i>	1	\$ 863.80	\$863.80
FRONT SUSPENSION LOWER ARM (RH) <i>7 distributor HL</i>	1	\$ 595.90	\$595.90
FRONT SHOCK ABSORBER ASSY (RH) <i>HL</i>	1	\$ 684.40	\$684.40
FRONT SHOCK ABSORBER MOUNTING (RH) <i>HL</i>	1	\$ 217.60	\$217.60
STG TIE ROD (RH) <i>HL</i>	1	\$ 186.40	\$186.40
STG TIE END (RH) <i>HL</i>	1	\$ 125.20	\$125.20
STABILIZER BAR ASSY <i>HL</i>	1	\$ 463.70	\$463.70
STABILIZER BAR LINK (RH) <i>HL</i>	1	\$ 85.90	\$85.90
ABS SENSOR <i>HL</i>	1	\$ 217.90	\$217.90
FRONT DRIVE SHAFT (RH) <i>HL</i>	1	\$ 2,061.60	\$2,061.60
RACK & PINION ASSY <i>HL</i>	1	\$ 1,820.00	\$1,820.00
SUB TOTAL			\$24,550.00
LESS 20%			\$4,910.00
DISCOUNTED TOTAL			\$19,640.00

✓ ~~526~~ 526.10 SN
 ✓ 1388.10
 ✓ 107.10
 3114.70
 2491.76

FRONT DOOR COLOUR COMFORT LOGO <i>rec</i>	SN	1	\$ 75.00	\$75.00	✓
FRONT TYRE (RH) <i>SN</i>	SN	1	\$ 216.00	\$216.00	X 601-10
SUB TOTAL				\$291.00	
Labour Charge					
Panel Beating		1	\$ 1,400.00	~~\$1,400.00~~	700/-
Spray Painting Charge		1	\$ 1,200.00	~~\$1,200.00~~	700/-
Wiring Charge		1	\$ 100.00	~~\$100.00~~	30/-
Tuff Kote		1	\$ 100.00	~~\$100.00~~	40/-
Towing Charge		1	\$ 80.00	\$80.00	44
Transfer of Door Mechanism FRONT		1	\$ 80.00	\$80.00	44 1530.00
Re-set Frt Power Window System		1	\$ 200.00	\$200.00	44
Four Wheel Alignment		1	\$ 120.00	~~\$120.00~~	60/-
Remove/Refix Undercarriage (Frt)		1	\$ 400.00	~~\$400.00~~	80/- 44
Re-set Frt ABS System		1	\$ 200.00	\$200.00	44
Remove/Refix Radiator		1	\$ 90.00	\$90.00	44
Remove/Refix Aircon & Refill Gas		1	\$ 130.00	\$130.00	44
Diagnostic & Resetting To Erase Fault Code		1	\$ 550.00	\$550.00	44
TOTAL LABOUR				\$4,650.00	
ESTIMATE TOTAL				\$ 24,581.00	
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance					

11/08/2021 @ 1300h

HA Author

1 hour 45 days.

2/1/2021

Repair limit

24k Auto

4622-86

4/5 3700/-

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: