(08/11/13) wef

ASS.REC.BY: MARCUS

REF: CS/ CT12100 8669/UVC

ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SDE 7030T

at Workshop m/s Koh motor

of

Insured:

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: **The veh had commenced its repair at the time of inspection.**

N/S	O/S

Bal. or Market Value: $ 96k.

IDAC Accident Rport: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 7 days Res.: Yes or No

Lum Sum: 15% % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted: MA 55038

Veh No: SDE 7030T Yr Regn: 16/3/21

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: Honda civic c.c 1597

Colour Grey A/C: Insured / Std / NI / NA

Sp.Reading 12968 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: MRHFC86OLT00015-79

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi : Nil / S/Rim / STD A/Rim or

Tyre Size: F: 215/55R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or hankook

Front		Rear	
R/Bal.	7 mm	R/Bal.	7 mm
L/Bal.	7 mm	L/Bal.	7 mm
D.O.A.	15/8/21	D.O.I.	23/8/21

Survey held at

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
13/10/21	Confirmed P/P & 8685-44 with posson

Date/Time, File Pass to? ☐ : Preli. Report

1) ☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee: ☐ : Site Insp ($) __S + RS__SI

☐ : Interview ($) Photos

☐ : Tech. Invs ($) Others

☐ : Weekend ($)

TOTAL

Report Format :

Lump Sum / I.B.I: ($)

HONDA

QUOTATION

KAH MOTOR CO. SDN. BHD.
(A Member of the Oriental Holdings Berhad)
Service and Body Repair
Tel: +65 6841 3838 Website: www.honda.com.sg
For 24-hours Roadside Assistance, Call 98203838

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer	: CHINA TAIPING INSURANCE (S'PORE) PTE 3 ANSON ROAD #16-00 SPRINGLEAF TOWER SINGAPORE 079909	**Document No.**	: SQT21002537	**Page**	1
		Date	: 16. Aug 2021		
		Customer No.	: WZC008		
		Svc Advisor	: YOU PO SOON		
Registration No	: SDE7030T	**Engine No**	: R16B25520799		
Chassis No	: MRHFC5650LT000579	**Date | Time**	: 16. Aug 2021 1:31:28 PM		
Model	: CIVIC 1.6 VTI YM2020	**Surveyor Name**	:		
Owner's Name	: PURETECH ENGINEERING PTE LTD	**Survey Date**	:		
Ins Policy No.	:	**Authorisation Date**	:		
Date of Accident	: 15/8/2021				

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount Incld GST
	TP DIRECT SETTLEMENT (J/NO:)						
	OWNER: PURETECH ENGINEERING PTE LTD						
	OWNER INSURER: TOKIO MARINE						
	ACC DATE: 15/08/2021						
	SURVEYED BY:						
	DATE:						
	REF NO:						
	TP INSURER: C/TAIPING						
	TP VEH: GQ8998X						
71500-TEC-Q00ZZ	FACE ASSY,RR.BUMPER	1	617.20	25	462.90	32.40	495.30
71510-TEA-T50	GARNISH ASSY,RR.BUMPER LOWER	1	128.50	25	96.37	6.75	103.12
71593-TEA-T01	SPACERR.RR.BUMPER SIDE	1	11.50	25	8.62	0.60	9.22
71598-TEA-T01	SPACERL.RR.BUMPER SIDE	1	11.50	25	8.62	0.60	9.22
91505-TM8-003	CLIP,BUMPER	7	2.30	25	12.07	0.84	12.91
71530-TEA-T00ZZ	BEAM COMPRR.BUMPER	1	188.00	25	141.00	9.87	150.87
66100-TEC-307ZZ	PANEL SETRR.	1	277.50	25	208.12	14.57	222.69
66114-TBA-A00ZZ	STIFFENER,R.RR.PANEL SIDE	1	30.50	25	22.87	1.60	24.47
66154-TBA-A00ZZ	STIFFENERL.RR.PANEL SIDE	1	30.50	25	22.87	1.60	24.47
68500-TEA-N00ZZ	LID COMP TRUNK	1	554.90	25	416.17	29.13	445.30
74865-TEA-T01	WEATHERSTRIPTRUNK LID	1	70.00	25	52.50	3.68	56.18
74890-TEA-T11ZB	GARNISH ASSYRR.LICENSE	1	114.80	25	86.10	6.03	92.13
74851-TEA-003	LOCK ASSYTRUNK	1	84.90	25	63.67	4.46	68.13
84640-TEA-Z01ZA	LINING ASSYRR.PANEL	1	50.30	25	37.72	2.64	40.36
75722-TBA-A00	EMBLEM SETRR.	1	13.40	25	10.05	0.70	10.75
75725-TEA-T01	EMBLEMRR.	1	12.50	25	9.37	0.66	10.03
75701-TBA-A10	EMBLEM,H-MARK	1	14.00	25	10.50	0.74	11.24
90301-ST0-003	NUTPUSH 3MM	2	2.10	25	3.15	0.22	3.37
33500-TEA-T01	TAILLIGHT ASSYR.	1	298.40	25	223.80	15.67	239.47

Printed on 16/8/2021 2:04:43 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of $53.50 (incl GST) will be applicable for the request of the above quotation for estimates above $2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

HONDA

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838 Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer	: CHINA TAIPING INSURANCE (S'PORE) PTE 3 ANSON ROAD #16-00 SPRINGLEAF TOWER SINGAPORE 079909	Document No.	: SQT21002537
		Date	: 16. Aug 2021
		Customer No.	: WZC008
		Svc Advisor	: YOU PO SOON
Registration No	: SDE7030T	Engine No	: R16B25520799
Chassis No	: MRHFC5650LT000579	Date | Time	: 16. Aug 2021 1:31:28 PM
Model	: CIVIC 1.6 VTI YM2020	Surveyor Name	:
Owner's Name	: PURETECH ENGINEERING PTE LTD	Survey Date	:
Ins Policy No.	:	Authorisation Date	:
Date of Accident	: 15/8/2021		

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount Incld GST
74940-SZW-003	BUZZER ASSYSMART 11	1	65.40	25	49.05	3.43	52.48
38387-TZ5-A01	ANTENNA ASSYL.F. 11	1	63.20	25	47.40	3.32	50.72
39530-TEA-H01	CAMERA ASSY,RR VI 11	1	360.20	25	270.15	18.91	289.06
39680-TEX-Y41ZT	SENSOR ASSY,PARKING Su	4	155.40	25	466.20	32.63	498.83
BO-NUM-COMP-L	NUMBER PLATE WITH CASING-L(N) SCR	1	45.00		45.00	3.15	48.15
				Sum Item	2774.27	194.20	2,968.47
BOSUN	SUNDRIES	1	50.00	20	50.00	3.50	53.50
BML02I	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER	1	180.00	120	180.00	12.60	192.60
BOJSE	BODY JOINT SEALANT.	1	100.00		100.00	7.00	107.00
BOBC	BODY UNDERSIDE COATING (N)	1	100.00		100.00	7.00	107.00
BP00R	APPLY BODY UNDERSIDE COATING (N).	1	250.00	200	250.00	17.50	267.50
BA02R	REMOVE & INSTALL REVERSE SENSORS-4 PCS (N)	1	200.00	130	200.00	14.00	214.00
BC011R	REMOVE INSTALL & CALIBRATE REAR VIEW CAMERA	1	450.00	350	450.00	31.50	481.50
BC012R	RESET VEHICLE SMART ENTRY SYSTEM	1	450.00	350	450.00	31.50	481.50
BMI03D	REMOVE & INSTALL REAR COMPARTMENT LININGS	1	650.00	350	650.00	45.50	695.50
BKTRR	REMOVE & TRANSFER ITEMS TO NEW TRUNK LID	1	450.00	350	450.00	31.50	481.50
BKRP02M	CUT OFF & RENEW RR PANEL. STRAIGHTEN ALIGN 650	1	3300.00	2600	3300.00	231.00	3531.00
BP06R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (6P) 520	1	3400.00	2600	3400.00	238.00	3638.00
				Sum Labor	9580.00	670.60	10,250.60
				Total Amount	12,354.27	864.80	13,219.07
				Total (Inclusive of GST)			13,219.07

Survey By: Meraus Mr

Date & Time: 23/8/21 @ 11.30am.

Excess: —

Status: Not Approved

Signature: telephone respraying 7days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Printed on 16/8/2021 2:04:43 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of $53.50 (incl GST) will be applicable for the request of the above quotation for estimates above $2,000.00. However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

12/10/2021 Attn: Marcus

Page 1/2

HONDA

SERVICE PRE-INVOICE

KAH MOTOR CO. SDN. BHD. WD: 7 Days.
(A Member of the Oriental Holdings Berhad)
370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022
255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer:	CU0001298 / CHINA TAIPING	**Document No:**	SVO21043165
Chassis No:	MRHFC5650LT000579	**Printed By:**	PSYOU
License No:	SDE7030T	**Order Date:**	21. August 2021
Mileage:	12968	**Order Time:**	10:01:03 AM
Engine No:	R16B25520799	**Service Advisor:**	YOU PO SOON

ITEM	DESCRIPTION	QTY	UNIT PRICE	DISC %	AMOUNT	7% GST Amount	Amount Incld GST
	TP DIRECT SETTLEMENT (J/NO: 76412)						
	OWNER: PURETECH ENGINEERING PTE LTD						
	OWNER INSURER: TOKIO MARINE						
	ACC DATE: 15/08/2021						
	SURVEYED BY: MARCUS CHUA						
	DATE: 23/8/2021						
	REF NO:						
	TP INSURER: C/TAIPING						
	TP VEH: GQ8998X						
71500-TEC-Q00ZZ	FACE ASSY,RR.BUMPER	1	617.20	25	462.90	32.40	495.30
71510-TEA-T50	GARNISH ASSY,RR.BUMPER LOWER	1	128.50	25	96.37	6.75	103.12
91505-TM8-003	CLIP,BUMPER	7	2.30	25	12.07	0.84	12.91
71530-TEA-T00ZZ	BEAM COMPRR.BUMPER	1	188.00	25	141.00	9.87	150.87
66100-TEC-307ZZ	PANEL SETRR.	1	277.50	25	208.12	14.57	222.69
66114-TBA-A00ZZ	STIFFENER,R.RR.PANEL SIDE	1	30.50	25	22.87	1.60	24.47
66154-TBA-A00ZZ	STIFFENERL.RR.PANEL SIDE	1	30.50	25	22.87	1.60	24.47
68500-TEA-N00ZZ	LID COMP TRUNK	1	554.90	25	416.17	29.13	445.30
75722-TBA-A00	EMBLEM SETRR.	1	13.40	25	10.05	0.70	10.75
75725-TEA-T01	EMBLEMRR.	1	12.50	25	9.37	0.66	10.03
75701-TBA-A10	EMBLEM,H-MARK	1	14.00	25	10.50	0.74	11.24
90301-ST0-003	NUTPUSH 3MM	2	2.10	25	3.15	0.22	3.37
			SUM PARTS:		**1,415.44**	**99.08**	**1,514.52**
BOSUN	0760 SUNDRIES	1	20.00		20.00	1.40	21.40
BML02I	EXT-YJ INSPECT RR LIGHTING MECHANISMS. PERFORM WATER TEST.(N)	1	120.00		120.00	8.40	128.40
BOJSE	0760 BODY JOINT SEALANT.	1	100.00		100.00	7.00	107.00
BOBC	1845 BODY UNDERSIDE COATING (N)	1	100.00		100.00	7.00	107.00
BP00R	1845 APPLY BODY UNDERSIDE COATING (N).	1	200.00		200.00	14.00	214.00
BA02R	EXT-YJ REMOVE & INSTALL REVERSE SENSORS-4 PCS (N)	1	130.00		130.00	9.10	139.10
BC011R	0760 REMOVE INSTALL & CALIBRATE REAR VIEW CAMERA	1	350.00		350.00	24.50	374.50
BC012R	0760 RESET VEHICLE SMART ENTRY SYSTEM	1	350.00		350.00	24.50	374.50
BMI03D	EXT-YJ REMOVE & INSTALL REAR COMPARTMENT LININGS GARNISHES.(N)	1	350.00		350.00	24.50	374.50
BKTRR	EXT-YJ REMOVE & TRANSFER ITEMS TO NEW TRUNK LID ADJUST & ALIGN.	1	350.00		350.00	24.50	374.50

2/2

HONDA

SERVICE PRE-INVOICE

KAH MOTOR CO. SDN. BHD.
(A Member of the Oriental Holdings Berhad)
370 Ubi Road 3 Singapore 408851. Tel: +65 6841 3883 Fax: +65 6741 5022
255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer:	CU0001298 / CHINA TAIPING	**Document No:**	SVO21043165
Chassis No:	MRHFC5650LT000579	**Printed By:**	PSYOU
License No:	SDE7030T	**Order Date:**	21. August 2021
Mileage:	12968	**Order Time:**	10:01:03 AM
Engine No:	R16B25520799	**Service Advisor:**	YOU PO SOON

BKRP02M	EXT-YJ CUT OFF & RENEW RR PANEL. STRAIGHTEN ALIGN FLOOR PANEL INCLUDING FITTINGS ON ATTACHMENT ITEM	1	2,600.00	2,600.00	182.00	2,782.00
BP06R	1865 SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (5P)	1	2,600.00	2,600.00	182.00	2,782.00
			SUM LABOUR:	**7,270.00**	**508.90**	**7,778.90**
			TOTAL SGD	8,685.44	607.98	9,293.42

Total Payable (SGD) **9,293.42**

GST Amount is calculated from individual line(s)

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	563R
Vehicle Details	
Vehicle No.:	SDE7030T
Vehicle to be Exported:	No
Intended Deregistration Date:	23 Aug 2021
Vehicle Make:	HONDA
Vehicle Model:	CIVIC 1.6 VTI CVT
Primary Colour:	Blue
Manufacturing Year:	2021
Engine No.:	R16B25520799
Chassis No.:	MRHFC5650LT000579
Maximum Power Output:	92.0 kW (123 bhp)
Open Market Value:	$19,880.00
Original Registration Date:	16 Mar 2021
First Registration Date:	16 Mar 2021
Transfer Count:	0
Actual ARF Paid:	$19,880.00 ๑๙๔๐
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	15 Mar 2031
PARF Rebate Amount:	$14,910.00
Intended COE Rebate Details	
COE Expiry Date:	15 Mar 2031
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	$41,996.00
COE Rebate Amount:	$40,128.00
Total Rebate Amount:	**$55,038.00**

The information contained herein is correct as at 23 Aug 2021

OK