(08/11/13) wef

ASSIGNED BY: Marcus

REF: CC6/1112100876 8/UP93

ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SJT 5709H

at Workshop m/s Choomoh

of

Insured: SHD 2370C

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: $23K.

IDAC Accident Rport: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 5 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted: Vehicle: IN / OUT 283A

Veh No: SJT 5709H Yr Regn: 19/10/09

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or CA1

Make: Volkswagen new golf c.c 1390

Colour Red A/C: Insured / Std / NI / NA

Sp.Reading 205272 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: WVWZZZ1KZAW030639

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi : Nil / S/Rim / STD A/Rim or

Tyre Size: F: 215/45ZR17

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or Tourador

Front		Rear	
R/Bal.	6 mm	R/Bal.	6 mm
L/Bal.	6 mm	L/Bal.	6 mm

D.O.A. 19/8/21 D.O.I. 20/8/21

Survey held at

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or O/S Rf.c

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction Bal 3yrs. 2nd Dep 7K.
COE until 18-10-2024 LTA $9659
WOH $13341 accident scene photo of folder
Dif hyper is Golf GTI type

25/8/21 L/S $6500 Confirmed with Alan.

Date/Time, File Pass to? ☐ : Preli. Report

1) ☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee: ☐ : Site Insp ($) __S + RS.__SI

☐ : Interview ($) Photos

☐ : Tech. Invs ($) Others

☐ : Weekend ($)

Report Format :

Lump Sum / I.B.I: ($)

TOTAL