ACCORD AUTO SERVICES PTE LTD

BLOCK 1009 BUKIT MERAH LANE 3
#01-80 SINGAPORE 159723
TEL:62715133/62717433, FAX:62745715

WIL R
4 dys
~~HS~~ PIP
M ~~AE~~ Sy
Before

Pg1

ESTIMATE REPAIR

Steve (LKK)
20/8/21, 4.30pm

China Taiping Insurance (Singapore) Pte Ltd

Date: 20.8.2021

Owner's Name : Lim Daniel

Vehicle No : SML9436A

Vehicle Make & Model : Mercedes Benz CLA200

Registration Date : 16 Jan 2014 (YOM 2013) COE Expiry Date 15 Jan 2024

Claim Type: Third Party Claim

Chassis No: WDD1173432N051199

DOA: 18.8.2021

No.	Description	Unit	List ($)
1	FRONT BONNET X NN	1	$ 2,658.98
2	FRONT RH FENDER X R	1	$ 870.65
3	FRONT RH FENDER SHIELD X NN	1	$ 268.98
4	FRONT BUMPER / BR	1	$ 1421.95 / 2,250.00
5	FRONT RH BUMPER SIDE RETAINER / BR	1	$ 105.00
6	FRONT BUMPER TOP INNER BRACKET ? X NN	1	$ 275.00
7	FRONT BUMPER RH INNER BRACKET ? X NN	1	$ 258.00
8	FRONT BUMPER RH NUZZLE COVER X NN	1	$ 95.00
9	FRONT BUMPER RH FOGLAMP GARNISH X NN	1	$ 116.85
10	FRONT RH BUMPER SENSOR ? X NN	1	$ 280.00
11	STEERING RACK X NN	1	$ 4,555.00
12	FRONT RH HEADLAMP / BR	1	$ 2632.90 / 2,680.40
13	FRONT RH HEADLAMP CONTROL UNIT (*Big) ? X NN	1	$ 831.60
14	FRONT RH HEADLAMP CONTROL UNIT (*Small) ? X NN	1	$ 365.00
15	FRONT RH HEADLAMP LOWER BRACKET ? X NN	1	$ 110.00
	4159.85		
	-10%		
	3743.86		
		Total (A) :	$ 15,720.46
		Less 10%	$ 1,572.05
		Total :	$ 14,148.41

Scanned with CamScanner

ACCORD AUTO SERVICES PTE LTD

BLOCK 1009 BUKIT MERAH LANE 3
#01-80 SINGAPORE 159723
TEL:62745133/ 62715433 FAX:62745135

STIMATE REPAIR

China Taiping Insurance (Singapore) Pte Ltd

Date: 20.8.2021

Owner's Name : Lim Daniel

Vehicle No : SML9436A

Vehicle Make & Model : Mercedes Benz CLA200

Registration Date : 16 Jan 2014 (YOM 2013) COE Expiry Date 15 Jan 2024

Claim Type: Third Party Claim

Chassis No: WDD1173432N051199

DOA: 18.8.2021

No	Description	Unit	List ($)
	Special Nett		
1	FRONT FENDER SHIELD CLIPS X M	SET	$ 70.00
2	FRONT BUMPER CLIPS / MPC	SET	$ 30 / 50.00
3	FRONT UNDER BUMPER COVER CLIPS & UNDER ENG CLIPS X M	SET	$ 60.00
4	TYRE	1	$ 420.00
	Labour		
1	Spray Painting to All Affected Areas(*Front RH Door)	1	$ 400 1,000.00
2	Labour Remove / Refix Accident Damages parts to knock , jack, cut weld and realign accident affected area	1	$ 300 1,000.00
3	Check Wiring System & Light	1	$ 50 100.00
4	Anti Rust Treatment	1	$ 30 120.00
5	To Check & Adjust Wheel Aligment	1	$ 60 100.00
6	To Remove/Replace Steering Rack	1	$ X 500.00
7	To Reprogramming Headlamp Control Unit	1	$ 100 380.00
8	Computer Diagnostic	1	$ 100 350.00
			1040 /
		Total (B) :	$ 4,150.00
		Grand Total:	$ 18,298.41

LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- [illegible]
- Replacement Parts(s) must be recovered and [illegible] Insurance Company

Acknowledged by Repairer
Signature:
Date:

P/P-4813.86

Scanned with CamScanner