LKK Auto Consultants Pte Ltd
Company Registration No. 199607198R
51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: S1M0350Y Date: 07th Sep 2021

Our Ref: CS3/ASM21000521/R1vf3e2-1

M/s Axa Insurance Pte Ltd
8 Shenton Way #24-01
Axa Tower
Singapore 068811
(The Motor Claims Department)

Attn: Yu Dominic Yishan

Dear Sir / Madam,

EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: SMM 1191C
INSURED VEHICLE: SHC 3680G
ACCIDENT DATE: 06/01/2021

We thank you for your instruction on 24/08/2021.

We acknowledge receipt of the following documents:-

a) Automobile Inspection Report of SMM 1191C from M/s Aeon Auto Consultants LLP.
b) Singapore Accident Statement of Vehicles SMM 1191C and SHC 3680G.
c) Final Repair Bill of SMM 1191C from M/s Alpha Performance Singapore Pte. Ltd.
d) Colour damaged vehicle photographs of SMM 1191C.

Pre-Repair Inspection Date : 12/01/2021 at M/s Alpha Performance Singapore Pte Ltd, 48 Toh Guan Road East #04-126, Enterprise Hub, Singapore 608586.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number	: SMM 1191C
Make & Model	: Toyota Noah Hybrid 1.8X CVT
Year of Registration	: 2019
Chassis Number	: ZWR800377784
Engine Capacity	: 1797 cc

2. We recommend that the repairs of the entire damage require about 5 (Five) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.