LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PRE-REPAIR INSPECTION REPORT

AXA INSURANCE PTE LTD

8 SHENTON WAY #24-01 AXA TOWER
SINGAPORE 068811

ATTN: ANG YVONNE

Ref: CS3/ASM21008979/Vtce2

Date: 09/09/2021

Code: ASM

1. Policy Particulars :- (THIRD PARTY CLAIM)

	Insured Veh.	SMD 6201Y	**Veh. Inspected**	GBH 9653R
	Policy No.	VPA/P2173755	**Coverage ($)**	0.00
	Claim No.	S1M03GFT	**Excess ($)**	0.00
	Assign From	ANG YVONNE	**Assign Date**	26/08/2021

2. Vehicle Particulars & Condition

	Make & Model	TOYOTA HIACE	**c.c**	2982
	Engine No.	HIDDEN	**Year of Reg.**	2018
	Chassis No.	JTFHT02P900246069	**Colour**	SILVER
	Odometer	66484 KM	**Steering**	IN ORDER
	Brakes	IN ORDER	**Modification**	SPORTS RIM
	General	GOOD		

3. Conditions of Tyres

		Size	**Make**	**Balance**
	R/H Front Tyre	195 R15C	MICHELIN	6 mm
	L/H Front Tyre	195 R15C	MICHELIN	6 mm
	R/H Rear Tyre	195 R15C	MICHELIN	6 mm
	L/H Rear Tyre	195 R15C	MICHELIN	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY.



5. General Information

	Accident Date	24/08/2021	**Inspect Date / Time**	30/08/2021 (11:00 AM)
	Survey held at	8, Kaki Bukit Avenue 4 @ Premier, #04-20		
	Repairer	A-TEC AUTOMOTIVE PTE LTD		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.
D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF $3,000-$4,000

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **3 Working Days**

Report Ref No. CS3/ASM21008979/Vtce2

Inspected By

THEVAN THOMAS KARTHIKESAVAN

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.