ASS. REC. BY: Steve / REPT CC4/AIG.2100 9068/GA3

ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD-RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S | O/S

Bal. or Market Value:

IDAC Accident Rport: Consistent? : Yes or No

SIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Cum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: FBP 7672G Yr Regn: 7/6/19

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: Honda CB400A c.c 399

Colour Red A/C: Insured / Std / Nil / N

Sp.Reading N/A T/Radio: Insured / Std / Nil / N

Eng/No:

C/No: JH2NC4295KKS90085

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Locked / Burnt or

Brake: Inorder / Jammed / Locked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 110-50R17

R: 140/50R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

R/Bal. 4 mm

U/Bal. mm

Rear

R/Bal. 4 mm

U/Bal. mm

D.O.A. 2/8/21 O.O.I. 30/8/21

Survey held at Southern Motor

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time	Action / Instruction
	MV-15K

Date/Time, File Pass to? : Prel. Report

: Final Report

Date/Time, File Return to?

Days Of Repair:

Resurvey No. of Trips:

Add Fee: : Site Insp ($)

: Interview ($)

: Tech. Inve ($)

: Weekend ($)

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

Special Format :

Lump Sum / I.P.J. / ...)

南方摩哆
Southern Motor

Business Reg. No: 234147-00L
Block 1006, Bukit Merah Lane 2, #01-10, Singapore 159762
Tel: 6273-0369 (3 Lines) Fax: 6274-6614

26-Aug-21

AIG Asia Pacific Insurance Pte Ltd
78 Shanton Way #07-16
AIG Building
Singapore (079120)

Steve (LKK)
30/8/21, 2.30pm
8322 8813

WTL
L/S
M/L by
3 days

Dear Sirs,

RE: Cost of repair to Honda CB400 – FBP7672G

1pc of Meter	CUT	S$	1,680.00
1pc of Clutch Lever	CUT		45.00
1pc of Handle Bar	BT		145.00
1pc of Front Head Lamp	BT		1,550.00
1pc of Mirror	CUT		95.00
1pc of Engine Guard	OD		160.00
1pc of Gear Lever	~~BT~~ BT		140.00
1pc of Front Footrest	MIS		65.00
1Set of Rear Footrest	CUT		55.00
1Set of Footrest Bracket	BT		225.00
1pc of Side Stand	BT		90.00
1pc of Handle Balancer	CUT		35.00
1pc of Fuel Tank (Local repair)	OD / CUT	400	1,580.00
1pc of CAM Cover (Local repair)	CUT	150	480.00
1pc of Gasket	N/C		65.00
1pc of Signal Light	CUT		75.00
1pc of Fork Oil Seal	N/C		60.00
			6,545.00
Less 10%			654.50
Nett			5,890.50
Transport			40.00
IU	CUT		165.00
Alignment Fork			100.00 50
Rear Box	CUT		350.00
Labor			350.00 250
			$6,895.50

Yours Faithfully,
Southern Motor