ASS. Filed By: GQ
PRS

REF: CS3/MSG20011243/Gvf3-1

ASSIGNMENT

From: Date:

Estimated Cost:

OD / [TP] / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s GARAGE 13

of

Insured: SLP 9053L

Policy No. 29141713MKF

Claims No. 629924

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

[ ] N/S	O/S

Bal. or Market Value:

IDAC Accident Rport: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: FBP 8999H Yr Regn: / 2019

Type: M.Car / [M.Cycle] / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: HONDA NSS300A c.c 279

Colour White A/C: Insured / Std / NI / NA

Sp.Reading 23799 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: MLHNF0798J * 5000564

Gen. Cond: [Good] / Fair / Poor / Burnt

Steering: [Inorder] / Jammed / Leaked / Burnt or

Brake: [Inorder] / Jammed / Leaked / Burnt or

Modi : [Nil] / S/Rim / STD A/Rim or

Tyre Size: F: 120/70-15

R: 140/70-14

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / [PIR] / SUMI / TOYO / YOKO or

Front		Rear	
R/Bal.	4 mm	R/Bal.	4 mm
L/Bal.	mm	L/Bal.	mm

D.O.A. 15/10/20 D.O.I. 16-10-2020

Survey held at W/S 5pm

Des. of Damages : Frt / Rear / O/S / [N/S] / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	$2000 - $3000
	No GIA provided
6/10/21	Submit LS $2,000 (Red 2700, 57%)

Date/Time, File Pass to? [ ] : Preli. Report

1) [ ] : Final Report

Date/Time, File Return to?

2) 6/10/21-typist

Days Of Repair: 3

Resurvey No. of Trip:

Add Fee: [ ] : Site Insp ($)

[ ] : Interview ($)

[ ] : Tech. Invs ($)

[ ] : Weeend ($)

Survey Fee:

Transportation: S + RS. SI

Photos

Other:

TOTAL