PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE	:	ACCIDENT REPAIRS
WORKSHOP	:	UBI ROAD 1
CONTACT NO	:	6366 2323
FAX NO	:	6841 1183
REFERENCE	:	PA/OD/0719/2021/JT
DATE	:	1-Sep-21
WIP	:	42281

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 2/9/21

AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120
Attn: Motor Claims Dept
Tel: 6880 4602 - Fax: 6880 4838

Hi Adrian
12 days exclude 1 Sunday
25-Oct-21
AMENDED 2 NOV 21

OWNER'S NAME	:	MR TAN SZE TONG
ADDRESS	:	8 ANG MO KIO AVENUE 2 #10-03 SINGAPORE 567695
TELEPHONE	:	HP +65 96806828
TYPE OF CLAIM	:	OWN DAMAGE CLAIM
POLICY NO	:	1800073045-03
VEHICLE NO	:	**SDZ 612 A**
MODEL CODE	:	A4 SEDAN 2.0 TFSI 8W
MODEL YEAR	:	6/26/2018
ENGINE NO	:	CVK 058801
CHASSIS NO	:	WAUZZZF40JA146757
MILEAGE	:	-
DATE IN	:	-
ESTIMATED BY	:	JOHNNY BOO / ALLAN WU
ACCIDENT DATE	:	1-Sep-21
PLACE OF ACCIDENT	:	SCHOOL OF THE ARTS ROUNDABOUT ENTRANCE

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SDZ 612 A

S/N	NATURE OF JOBS			ESTIMATED CHARGES		SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N	$	480.00	$	480.00
2	TO REMOVE AND TRANSFER RHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N	$	350.00	$	250.00
3	TO REMOVE AND REINSTALL AIRCON CONDENSER, ADDITIONAL RADIATOR AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM. TO CARRY OUT VACUUM AND REGAS.	S/N	$	1,400.00	$	1,400.00
4	TO RENEW FRONT WINDSCREEN.	S/N	$	480.00	$	480.00
5	TO INSTALL SOLAR FILM FOR FRONT WINDSCEEN.	S/N	$	400.00	$	400.00
6	TO RENEW FRONT WINDSCREEN SENSOR FOIL AND RESET SYSTEM.	S/N	$	300.00	$	300.00
	SUB - TOTAL LABOUR CHARGES	:	**$**	**3,410.00**	**$**	**3,310.00**

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SDZ 612 A

S/N	NATURE OF JOBS			ESTIMATED CHARGES		*SURVEYOR'S RECOMMENDATIONS*
	c/f				*$*	*3,310.00*
7	TO CARRY OUT WATER SEEPAGE TEST FOR FRONT WINDSCREEN.	S/N	$	200.00	*$*	*150.00*
8	TO REMOVE AND RENEW RHS FRONT WHEEL SUSPENSION ASSY WITH SUBFRAME.	S/N	$	2,400.00	*$*	*2,400.00*
9	TO REMOVE AND TRANSFER RHS FRONT DOOR 'S MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES.	S/N	$	350.00	*$*	*280.00*
10	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET, RHS FRONT FENDER, RHS FRONT DOOR AND RHS HEADLIGHT. TO CUT OUT AND WELD RHS FRONT RHS FRONT DOOR AND RHS HEADLIGHT. TO CUT OUT AND WELD RHS FRONT TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.		$	8,050.00	*$*	*3,750.00*
11	TO RESPRAY FRONT BUMPER, BONNET, HINGES, RHS FRONT FENDER, RHS FRONT FENDER TOP SUPPORT, RHS FRONT DOOR, RHS WING MIRROR COVER AND RHS A-PILLAR.		$	6,000.00	*$*	*2,475.00*
12	TO RENEW RHS FRONT RIM WITH TYRE. TO CARRY OUT PRE/POST WHEEL ALIGNMENT.		$	520.00	*$*	*520.00*
	SUB - TOTAL LABOUR CHARGES	**:**	**$**	**17,520.00**	*$*	*12,885.00*

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SDZ 612 A

S/N	NATURE OF JOBS			ESTIMATED CHARGES		*SURVEYOR'S RECOMMENDATIONS*
	c/f				***$***	***12,885.00***
13	TO TOW BACK THE VEHICLE FROM ACCIDENT SCENE.	S/N	$	280.00		
14	TO CARRY OUT FIRST MESASUREMENT ON CAR-O-LINER.	S/N	$	800.00	***$***	***800.00***
15	TO PLACE THE VEHICLE ON CAR-O-LINER TO FACILITATE THE REPAIR.	S/N	$	2,400.00	***$***	***2,400.00***
16	TO CARRY OUT PRE/POST DIAGNOSTIC CHECK.	S/N	$	384.00	***$***	***384.00***
	TOTAL LABOUR CHARGES	**:**	**$**	**24,794.00**	***$***	***16,469.00***

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SDZ 612 A

			DAMAGED PARTS & PRICES			
S/N	**PARTS DESCRIPTION**	**QTY**		**S/NETT**		***REMARKS***
1	FRONT BUMPER	1	$	1,787.00	$	1,429.60
2	FRONT BUMPER FIXING PARTS	1		TBC		
3	FRONT BUMPER SECURING STRIP	2	$	71.00	$	56.32
4	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	1	$	210.00		
5	FRONT BUMPER AIR GUIDE - RH	1	$	63.00	$	50.08
6	FRONT BUMPER AIR GUIDE GRILLE - RH	1	$	365.00	$	292.00
7	FRONT BUMPER GUIDE SECTION - RH	1	$	38.00	$	29.84
8	HORN - RH	1	$	126.00		
9	HORN BRACKET - RH	1	$	29.00		
10	FRONT FENDER - RH	1	$	767.00	$	613.20
11	FRONT FENDER ATTACHMENT PARTS	1	$	202.00		
12	FRONT FENDER CLOSING ELEMENT	1	$	72.00	$	57.52
13	FRONT FENDER TOP BRACKET - FRONT RH	1	$	35.00	$	27.92
14	FRONT FENDER DEFORMATION BRACKET - RH	1	$	49.00	$	39.20
15	RIVET	6	$	20.00	$	15.84
16	FRONT FENDER TOP BRACKET - REAR RH	1	$	32.00	$	25.12
17	FRONT FENDER BRACE - RH	1	$	118.00	$	94.40
18	FRONT WHEEL HOUSING LINER - RH	1	$	241.00	$	192.80
19	FRONT WHEEL HOUSING LINER ATTACHMENT PARTS	1		TBC		
20	FRONT WHEEL SPOILER	1	$	73.00	$	58.40
	SUB TOTAL SPARE PARTS	**:**	**$**	**4,298.00**	**$**	**2,982.24**

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APROVED
SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SDZ 612 A

				DAMAGED PARTS & PRICES		
S/N	**PARTS DESCRIPTION**	**QTY**		**S/NETT**		***REMARKS***
		C/F			***$***	***2,982.24***
21	FRONT WHEEL SPOILER TRIM - RH	1	$	36.00	***$***	***28.56***
22	FRONT FENDER STONE CHIP GUARD - RH	1	$	51.00	***$***	***40.32***
23	FRONT FENDER TOP COVER - RH	1	$	31.00	***$***	***24.64***
24	FRONT HEADLIGHT CORNER COVER - RH	1	$	23.00	***$***	***17.92***
25	BONNET	1	$	3,246.00	***$***	***2,596.80***
26	BONNET ATTACHMENT PARTS	1	$	412.00		
27	BONNET HINGE - LH / RH	2	$	610.00		
28	BONNET IMPACT PROTECTOR - LH / RH / CENTER	1	$	84.00	***$***	***65.68***
29	BONNET STRIKER	1	$	50.00		
30	BONNET LOCK	1	$	214.00		
31	HEADLIGHT - RH	1	$	7,693.00	***$***	***6,154.40***
32	HEADLIGHT LIFT CYLINDER - RH	1	$	210.00		
33	HEADLIGHT LIFT CYLINDER HOSE	1	$	93.00		
34	LOCK CARRIER	1	$	1,016.00	***$***	***812.80***
35	COOLANT	6	$	266.00	***$***	***212.64***
36	FRONT FENDER CONNECTING PLATE - RH	2	$	468.00		
37	WATER RESERVOIR	1	$	251.00		
38	FRONT WINDSCREEN	1	$	147.00	***$***	***900.00***
39	FRONT WINDSCREEN FOIL	1	$	1,125.00	***$***	***109.20***
40	FRONT WINDSCREEN RETAINING SPRING	1	$	137.00	***$***	***16.56***
	SUB-TOTAL SPARE PARTS	**:**	**$**	**16,163.00**	***$***	***13,961.76***

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APROVED
SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SDZ 612 A

				DAMAGED PARTS & PRICES		
S/N	**PARTS DESCRIPTION**	**QTY**		**S/NETT**		***REMARKS***
		C/F			***$***	***13,961.76***
41	FRONT WINDSCREEN SPRING CLIP	1	$	21.00	***$***	***16.56***
42	PRIMER	1	$	20.00	***$***	***15.76***
43	FRONT DOOR - RH	1	$	3,192.00	***$***	***2,553.60***
44	FRONT DOOR OUTER SEAL - R	1	$	205.00	***$***	***164.00***
45	BONDING AGENT	1	$	49.00		
46	CLEANING SOLUTION	1	$	68.00		
47	APPLICATOR	1	$	8.00		
48	BUNGS	1	$	4.00		
49	FRONT DOOR ATTACHMENT PARTS	1		TBC		
50	FRONT DOOR CATCH - RH	1	$	105.00		
51	TYRE PRESSURE STICKER	1	$	38.00	***$***	***29.84***
52	FRONT WINDOR REGULATOR - RH	1	$	282.00		
53	FRONT WINDOR REGULATOR MOTOR - RH	1	$	313.00		
54	REAR VIEW MIRROR	1	$	1,079.00		
55	REAR VIEW MIRROR TOP COVER	1	$	32.00		
56	FRONT MIRROR MOUNTING - RH	1	$	897.00		
57	FRONT RIM - RH	1	$	1,690.00	***$***	***1,352.00***
58	FRONT SUB FRAME	1	$	1,891.00		
59	FRONT WISHBOON LINK - RH	1	$	539.00	***$***	***430.80***
60	FRONT SUSPENTION GUIDE - RH	1	$	943.00	***$***	***754.40***
	SUB-TOTAL SPARE PARTS	**:**	**$**	**11,376.00**	***$***	***19,278.72***

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APROVED
SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SDZ 612 A

				DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY		S/NETT		*REMARKS*
		C/F			*$*	*19,278.72*
61	FRONT UPPER ARM - RH	2	$	1,024.00	*$*	*818.40*
62	FRONT WHEEL BEARING HOUSING - RH	1	$	968.00	*$*	*774.00*
63	FRONT SWIVEL JOINT - RH	1	$	193.00	*$*	*154.40*
64	FRONT WHEEL HUB - RH	1	$	479.00	*$*	*383.20*
65	FRONT WHEEL BEARING - RH	1	$	246.00	*$*	*196.80*
66	FRONT SUSPENSION FORKS - RH	1	$	264.00		
67	FRONT COUPLING ROD - RH	1	$	127.00		
68	FRONT ANTI ROLL BAR	1	$	433.00		
69	FRONT DRIVE SHAFT - RH	1	$	2,650.00		
70	FRONT SHOCK ABSORBER - RH	1	$	301.00	*$*	*240.40*
71	FRONT STEERING RACK	1	$	6,787.00		
72	FRONT TRACK ROD - RH	1	$	99.00	*$*	*78.88*
73	FRONT TIE ROD END - RH	1	$	197.00	*$*	*157.20*
74	FRONT LOWER NOISE INSULATION	1	$	572.00		
75	FRONT DOOR WINDOW CHROME SLOT SEAL - RH	1	$	307.00		
76	ACRYLIC SEALANT	S/N	$	180.00		
77	CRAVITY WAX	S/N	$	140.00		
78	METAL FILER POWER	S/N	$	280.00		
79	STONE CHIPS	S/N	$	180.00		
80	FRONT WINDSCREEN SEALANT	S/N	$	200.00	*$*	*200.00*
81	**Added parts - see attached**		$	2,754.00	*$*	*370.00*
82	**Added parts - see attached**		$	39.00	*$*	*30.80*
83	SUNDRIES		$	500.00	*$*	*362.96*
	TOTAL SPARE PARTS	:	**$**	**50,757.00**	*$*	*23,045.76*
	TOTAL LABOUR CHARGES	:	**$**	**24,794.00**	*$*	*16,469.00*
	GRAND TOTAL	:	**$**	**75,551.00**	*$*	*39,514.76*

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APROVED
SPARE PARTS ARE SPECIAL NETT.
bl-22/10/21

PREMIUM AUTOMOBILES
55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183
Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Supplementary Estimate - 2

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept **Tel: 6841 0055 / Fax: 6256 4315**	**Estimate No.** **Date** **Service Advisor** **Pages** **Regn No** **Model No**	PA/OD/0719/2021/JT 13-Sep-21 CHANG 1 of 1 SDZ 612 A AUDI A4 SEDAN 2.0 TFSI

Quantity	Description	Unit Price	Amount
Parts			
1	FRONT TYRE - RHS	$ 370.00	***$ 370.00***
2	SUSPENSION STRUT DOME - RH	$ 1,912.00	
3	SUSPENSION CONSOLE - RH	$ 472.00	
	GRAND TOTAL	**$ 2,754.00**	***$ 370.00***

For Premium Automobiles Pte Ltd

Authorised Signature

PREMIUM AUTOMOBILES
55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183
Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Supplementary Estimate

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept **Tel: 6841 0055 / Fax: 6256 4315**	**Estimate No.** **Date** **Service Advisor** **Pages** **Regn No** **Model No**	PA/OD/0719/2021/JT 9-Sep-21 CHANG 1 of 1 SDZ 612 A AUDI A4 SEDAN 2.0 TFSI

Quantity	Description	Unit Price	Amount
Parts			
1	HEADLIGHT WASHER PIPE	$ 39.00	***$ 30.80***
	GRAND TOTAL	**$ 39.00**	***$ 30.80***

For Premium Automobiles Pte Ltd

Authorised Signature

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT