SMO CS3/SMO21000378/GUtf3-1

... By: GL PRS

ASSIGNMENT

Vehicle No: GBG2542D ... Regn 06 Jul 2017

Type: M.Car / M.Cycle / Bus / (Van) / Lorry / Taxi / Prime Mover / Truck / Trailer or

Date

...imated Cost

... / (TP) WS / TP RES / OD RES / EVA / INV / MV

Inspect Vehicle No:

Workshop m/s Garage 13

Make: Toyota Hiace c.c. 2982

Colour: silver A/C: Insured / Std / NI / NA

Sp Reading: 112271 T/Radio: Insured / Std / NI / NA

Eng/No

C/No: JTFHT02P800.218849

Gen Cond: (Good) / Fair / Poor / Burnt

Steering: (Inorder) / Jammed / Leaked / Burnt or

Brake: (Inorder) / Jammed / Leaked / Burnt or

Modi: (Nil) / S/Rim / STD A/Rim or

Tyre Size: F: 195R15

R: 〃

(BS) / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

...sured:

...licy No.

...aims No

...m Insured: Excess:

(Client's Record)

...ake of Veh:

(Policy Condition)

...emark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Front			Rear		
R/Bal	6	mm	R/Bal	6	mm
L/Bal	6	mm	L/Bal	6	mm

D.O.A. D.O.I. 11-01-21

...al. or Market Value:

...DAC Accident Rport — Consistent? : Yes or No

...IA / PR Seen: — Consistent? : Yes or No

...st. Repairs: 8 days — Res.: Yes or No

...um Sum: % — 3 Val: Yes or No

Survey held at w/s 1:20pm

Des. of Damages: (Frt) / (Rear) / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

...A / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date — Person Contacted

Date / Time	Action / Instruction
	$7000 – $8000

SUBMIT LUMP SUM $8000,
RED: 3100;27%

Date/Time, File Pass to: [ ] : Preli. Report

[ ] : Final Report

Date/Time, File Return to:

Days Of Repair: 8

Resurvey No. of Trip: 1

Survey Fee:

Transportation

Add Fee: [ ] Site Insp: ($

[ ] Interview: ($