

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
 GST:201001158E RCB NO:201001158E

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY
 #07-16 AIG BUILDING
 SINGAPORE 079120

TEL: 64193000

FAX: 64153727

ATTN: Motor Claim Department

WS Ref: TP/AIG/AMK

Claim Type: Third Party

Accident Date: 12/09/2021

TP Veh Reg No: SKX9215G

Estimate No: ES2190872/AMK

Date: 14 Sep 2021

Policy No: 5115943957-01 PREMIUM

Veh Reg No: SLQ2034H

Make/Model: HONDA VEZEL

Chassis No: RU31245325

Engine No: LEB5945347

Reg. Date: 29/06/2017

Not Authorized
L/Ry &
Heavy After Pain
26 days

Estimate Repair Cost to Vehicle No :SLQ2034H

Description	U/Price	Quantity	List Price	Amount
			S\$	S\$
List Price				
1 FRONT BUMPER	801.20	1 PC	<i>Tn</i> 801.20	
2 FRONT BUMPER REINFORCEMENT	321.40	1 PC	<i>Bu</i> 321.40	
3 FRONT BUMPER CENTRE LOWER GRILLE	77.40	1 PC	<i>CM</i> 77.40	
4 FRONT BUMPER TOW HOOK COVER	27.10	1 PC	<i>mi</i> 27.10	
5 FRONT BUMPER FOG LAMP GARNISH	45.20	2 PC	<i>Di</i> 90.40	
6 FRONT BUMPER RH FOG LAMP	327.70	1 PC	<i>Bu</i> 327.70	
7 FRONT BUMPER RH FOG LAMP HOLDER	51.30	1 PC	<i>CM</i> 51.30	
8 FRONT BUMPER SIDE RETAINER	20.60	2 PC	<i>CM</i> 41.20	
9 FRONT BUMPER CLIP	3.50	6 PC	<i>nc</i> 21.00	
10 FRONT BUMPER LOWER SPOILER	381.20	1 PC	<i>Di</i> 381.20	
11 BONNET	892.40	1 PC	<i>Bu</i> 892.40	
12 BONNET HINGE	45.80	2 PC	<i>Di</i> 91.60	
13 BONNET INNER LOCK	98.20	1 PC	<i>Bu</i> 98.20	
14 BONNET INSULATOR	122.90	1 PC	<i>Tn</i> 122.90	
15 BONNET CLIP	3.50	6 PC	<i>nc</i> 21.00	
16 BONNET RH INNER RUBBER	37.50	1 PC	<i>WT</i> 37.50	
17 FRONT GRILLE HOUSING	351.80	1 PC	<i>CM</i> 351.80	
18 FRONT GRILLE OUTER GARNISH	421.90	1 PC	<i>CM</i> 421.90	
19 FRONT GRILLE CHROME MOULDING	95.20	1 PC	<i>nc</i> 95.20	
20 FRONT GRILLE LOGO	24.70	1 PC	<i>nc</i> 24.70	
21 FRONT GRILLE CENTRE BRACKET	38.70	1 PC	<i>Bu</i> 38.70	
22 FRONT GRILLE SIDE BRACKETS	17.60	2 PC	<i>CM</i> 35.20	
23 HEADLAMP	<i>ols Bu</i> 1,794.20	2 PC	<i>ols mfg CM</i> 3,588.40	
24 HEADLAMP LOWER BRACKET	35.40	2 PC	<i>CM</i> 70.80	
25 HORN RH	39.70	1 PC	<i>nc</i> 39.70	
26 FUSE BOX ASSY	980.70	1 PC	<i>CM</i> 980.70	
27 FRONT FENDER	<i>ols Bu</i> 558.70	2 PC	<i>ols Bu</i> 1,117.40	
28 FRONT FENDER EMBLEM	<i>nc</i> 58.70	2 PC	<i>nc</i> 117.40	
29 FRONT FENDER INNER SHIELD	<i>ols Tn</i> 136.90	2 PC	<i>ols Tn</i> 273.80	
30 FRONT FENDER INNER SHIELD CLIP	<i>nc</i> 3.50	12 PC	<i>nc</i> 42.00	
31 FRONT FENDER WHEEL ARCH GARNISH	<i>Bu</i> 195.20	2 PC	<i>Bu</i> 390.40	
32 FRONT RH FENDER EXTENSION ARM	<i>Bu</i> 120.70	1 PC	<i>Bu</i> 120.70	
33 FRONT RH FENDER INNER CENTRE ARM	<i>Bu</i> 50.40	1 PC	<i>Bu</i> 50.40	
34 FRONT RH FENDER OUTER CENTRE ARM	<i>Bu</i> 76.20	1 PC	<i>Bu</i> 76.20	
35 FRONT RH FENDER INNER PANEL	<i>Bu</i> 115.20	1 PC	<i>Bu</i> 115.20	
36 FRONT RH WHEEL HOUSING	<i>Bu</i> 406.20	1 PC	<i>Bu</i> 406.20	
37 FRT SUPPORT PANEL	<i>Bu</i> 578.20	1 PC	<i>Bu</i> 578.20	
38 FRONT SUPPORT PANEL INNER TOP GARNISH	<i>CM</i> 85.90	1 PC	<i>CM</i> 85.90	

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120

TEL: 64193000 FAX: 64153727

ATTN: Motor Claim Department

WS Ref: TP/AIG/AMK

Claim Type: Third Party

Accident Date: 12/09/2021

TP Veh Reg No: SKX9215G

Estimate No: ES2190872/AMK

Date: 14 Sep 2021

Policy No: 5115943957-01 PREMIUM

Veh Reg No: SLQ2034H

Make/Model: HONDA VEZEL

Chassis No: RU31245325

Engine No: LEB5945347

Reg. Date: 29/06/2017

Estimate Repair Cost to Vehicle No :SLQ2034H

Description	U/Price	Quantity	List Price	Amount
			SS	SS
39 FRONT SUPPORT PANEL INNER TOP GARNISH CLIP	3.50	6 PC	21.00	—
40 RADAR SENSOR ASSY BRACKET	580.70	1 PC	580.70	—
41 RADAR SENSOR ASSY	2,850.70	1 PC	2,850.70	X
42 ABS PUMP ASSY	2,738.90	1 PC	2,738.90	—
43 WIPER WASHER TANK	75.20	1 PC	75.20	—
44 WIPER WASHER NECK	28.30	1 PC	28.30	—
45 WIPER WASHER MOTOR	89.20	1 PC	89.20	—
46 FRONT WIPER PANEL GARNISH	240.70	1 PC	240.70	—
47 FRT LOWER CENTRE UNDER COVER	96.80	1 PC	96.80	—
48 AIR-CON CONDENSER	750.20	1 PC	750.20	—
49 RADIATOR	1,376.20	1 PC	1,376.20	—
50 RADIATOR RH SIDE GARNISH	30.40	1 PC	30.40	—
51 RH ENGINE MOUNTING	184.90	1 PC	184.90	—
52 ENGINE LH MOUNTING	335.20	1 PC	335.20	—
53 SPORT RIM	765.90	4 PC	3,063.60	—
54 FRONT RH DOOR	956.20	1 PC	956.20	—
55 FRONT RH DOOR FRAME STICKER	25.70	1 PC	25.70	—
56 FRONT RH DOOR CHECKER	59.20	1 PC	59.20	—
57 FRONT RH DOOR TOP HINGE	45.20	1 PC	45.20	—
58 FRONT RH DOOR BOTTOM HINGE	59.20	1 PC	59.20	—
59 FRONT RH DOOR SPEAKER	120.70	1 PC	120.70	—
60 FRONT RH DOOR POWER WINDOW MOTOR & REGULATOR	400.70	1 PC	400.70	—
61 FRONT RH DOOR WIRE HARNESS	590.00	1 PC	590.00	—
62 FRONT RH DOOR INNER LOCK	262.90	1 PC	262.90	—
63 REAR RH DOOR	930.20	1 PC	930.20	—
64 REAR RH DOOR FRAME STICKER	28.30	1 PC	28.30	—
65 REAR RH DOOR INNER LOCK	220.90	1 PC	220.90	X
66 REAR RH DOOR TOP HINGE	40.10	1 PC	40.10	—
67 REAR RH DOOR BOTTOM HINGE	40.10	1 PC	40.10	—
68 REAR RH DOOR CHECKER	55.90	1 PC	55.90	—
69 REAR RH DOOR POWER WINDOW MOTOR & REGULATOR	378.90	1 PC	378.90	—
70 RH B PILLAR	725.40	1 PC	725.40	—
71 REAR RH WHEEL ARCP GARNISH	195.20	1 PC	195.20	—
72 FRONT WINDSCREEN GLASS MOULDING	207.40	1 PC	207.40	—
73 FRONT AIRBAG SENSOR	250.40	1 PC	250.40	—
74 AIR BAG ECU	980.90	1 PC	980.90	—
75 DASHBOARD ASSY	800.60	1 PC	800.60	—
76 PASSENGER FRT AIR BAG	2,236.70	1 PC	2,236.70	—
77 STEERING AIRBAG	1,605.90	1 PC	1,605.90	—

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
 GST:201001158E RCB NO:201001158E

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY
 #07-16 AIG BUILDING
 SINGAPORE 079120

TEL: 64193000 FAX: 64153727

ATTN: Motor Claim Department

WS Ref: TP/AIG/AMK

Claim Type: Third Party

Accident Date: 12/09/2021

TP Veh Reg No: SKX9215G

Estimate No: ES2190872/AMK

Date: 14 Sep 2021

Policy No: 5115943957-01 PREMIUM

Veh Reg No: SLQ2034H

Make/Model: HONDA VEZEL

Chassis No: RU31245325

Engine No: LEB5945347

Reg. Date: 29/06/2017

Estimate Repair Cost to Vehicle No :SLQ2034H

Description	U/Price	Quantity	List Price	Amount
			<u>S\$</u>	<u>S\$</u>
78 STEERING SPIRAL CABLE	389.20	1 PC	389.20	✓
79 FRONT SEAT BELT	789.70	2 PC	1,579.40	✓
80 FRONT SEAT BELT LOWER CENTRE GARNISH	129.40	2 PC	258.80	✓
81 SIDE AIR BAG	860.20	2 PC	1,720.40	✓
82 ROOF LINING	1,250.70	1 PC	1,250.70	✓
83 FRONT RH SEAT AIRBAG	850.00	1 PC	850.00	✓
84 FRONT RH SHOCK ABSORBER	430.20	1 PC	430.20	✓
85 FRONT RH TOP MOUNTING	29.70	1 PC	29.70	✓
86 FRONT RH LOWER ARM	350.70	1 PC	350.70	✓
87 FRONT RH BALL JOINT	98.70	1 PC	98.70	✓
88 FRONT RH KNUCKLE ARM	259.70	1 PC	259.70	✓
89 FRONT RH WHEEL HUB	187.20	1 PC	187.20	✓
90 FRONT RH WHEEL HUB BEARING	138.50	1 PC	138.50	✓
91 FRONT RH DRIVESHAFT	1,100.20	1 PC	1,100.20	✓
92 FRONT RH STAY LINKAGE	60.40	1 PC	60.40	✓
93 FRONT CROSSMEMBER	795.20	1 PC	795.20	✓
94 STEERING RACK ASSY	1,172.90	1 PC	1,172.90	✓
95 STEERING RH TIE ROD END	71.80	1 PC	71.80	✓
			46,846.80	
		Less 20%	9,369.36	37,477.44
Special Net				
96 FRONT NUMBER PLATE	35.00	1 PC	35.00	✓
97 COOLANT	40.00	1 PC	40.00	✓
98 FRONT WINDSCREEN GLASS SEALANT	40.00	1 PC	40.00	✓
99 SIDE SKIRT	350.00	1 SET	350.00	✓
100 FRONT RH TYRE	180.00	1 PC	180.00	30 is
101 BRAKE FLUID 2 LITRES	20.00	1 PC	20.00	✓
			665.00	665.00
Labour				
102 TOWING (CRANE/WINCH UP)	170.00	1 LA	170.00	✓
103 REMOVE AND REFIX AIRCON,CHECK,VACUUM & REFILL GAS	100.00	1 LA	100.00	✓
104 REMOVE AND REFIX FRONT WINDSCREEN GLASS	120.00	1 LA	120.00	✓

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
 GST:201001158E RCB NO:201001158E

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY
 #07-16 AIG BUILDING
 SINGAPORE 079120

TEL: 64193000

FAX: 64153727

ATTN: Motor Claim Department

WS Ref: TP/AIG/AMK

Claim Type: Third Party

Accident Date: 12/09/2021

TP Veh Reg No: SKX9215G

Estimate No: ES2190872/AMK

Date: 14 Sep 2021

Policy No: 5115943957-01 PREMIUM

Veh Reg No: SLQ2034H

Make/Model: HONDA VEZEL

Chassis No: RU31245325

Engine No: LEB5945347

Reg. Date: 29/06/2017

Estimate Repair Cost to Vehicle No :SLQ2034H

Description	U/Price	Quantity	List Price	Amount
			<u>S\$</u>	<u>S\$</u>
105 REMOVE & REFIX FRT BUMPER & ATTACHMENTS,GRILLE,BONNET & ATTACHMENTS,BOTH FENDERS,HEADLAMPS,BOTH RH DOORS & ATTACHMENTS;TO CUT,WELD & RENEW FRT SUPPORT PANEL,FRT RH WHEEL HOUSING,RH B-PILLAR;KNOCKING & REPAIR FRT RH A PILLAR,RH ROCKER PANEL & REALIGN SAME	2,200.00	1 LA	2,200.00	2000
106 PUTTY & RESPRAY FRT BUMPER,LOWER SPOILER,BONNET,BOTH FENDERS,BOTH RH DOORS,REAR RH SIDE BUMPER,REAR RH FENDER,FRT SUPPORT PANEL,RH B PILLAR,RH ROCKER PANEL,BOTH RH WHEEL ARCH GARNISHS,FRT LH WHEEL ARCP GARNISH & ALL AFFECTED AREAS	2,000.00	1 LA	2,000.00	1900
107 REMOVE & REFIX BOTH RH DOORS,WINDOW GLASSES & RESET CENTRAL LOCKINGS	120.00	1 LA	120.00	✓
108 REMOVE & REFIX DASHBOARD ASSY TO FACILIATE REPAIR	250.00	1 LA	250.00	✓
109 REMOVE & REFIX FRT SEATS,ROOF LINING,CARPET TO FACILITATE REPAIR	180.00	1 LA	180.00	150
110 REMOVE & REFIX FRT SEAT BELTS,AIRBAG ECU,STEERING AIRBAG,PASSENGER AIRBAG & REALIGN THE SAME	250.00	1 LA	250.00	200
111 REMOVE & REFIX AIRBAG ECU,REPROGRAMME & RESET FAULT CODE	200.00	1 LA	200.00	✓
112 REMOVE & REFIX ENGINE MOUNTINGS,FRT RH UNDERCARRIAGE,STEERING RACK ASSY,DRIVESHAFT,CROSSMEMBER & REALIGN THE SAME	350.00	1 LA	350.00	✗
113 TO CONDUCT COMPUTERIZED WHEEL ALIGNMENT	80.00	1 PC	80.00	✓
114 TO MOUNT ON CAR-O-LINER,JACK & STRAIGHTEN CHASSIS	250.00	1 LA	250.00	✗
115 REMOVE & REFIX SPORT RIMS X4, TYRES,BALANCE & REALIGN THE SAME	160.00	1 LA	160.00	120
116 REMOVE & REFIX ABS PUMP ASSY & BLEED BRAKE SYSTEM	180.00	1 LA	180.00	120
117 RUSTPROOFING	180.00	1 LA	180.00	✓
118 TO APPLICATION,BREAK AND RESEAL FRT NUMBER PLATE (OPC) , RESEAL & EDAY LICENCE	80.00	1 LA	80.00	✓
119 REMOVE & REFIX RADAR SYSTEM & CALIBRATE	200.00	1 LA	200.00	150
			7,070.00	7,070.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY

#07-16 AIG BUILDING
SINGAPORE 079120

TEL: 64193000

ATTN: Motor Claim Department

WS Ref: TP/AIG/AMK

Claim Type: Third Party

Accident Date: 12/09/2021

TP Veh Reg No: SKX9215G

FAX: 64153727

Estimate No: ES2190872/AMK
Date: 14 Sep 2021
Policy No: 5115943957-01 PREMIUM
Veh Reg No: SLQ2034H
Make/Model: HONDA VEZEL
Chassis No: RU31245325
Engine No: LEB5945347
Reg. Date: 29/06/2017

Estimate Repair Cost to Vehicle No :SLQ2034H

Description	U/Price	Quantity	List Price	Amount
			S\$	S\$
			Total	S\$ 45,212.44
			Add GST @ 7%	3,164.87
			Total Amount Payable	S\$ 48,377.31

* SURVEY VEHICLE AT ANG MO KIO WORKSHOP

For Cheng Hoe Motor Pte Ltd

Dorlyn LA

AUTHORISED SIGNATURE