Surveyor:

REF: CS1/LAW21009656/Uvf3

Special Instruction:

L/SUM : $ 15,600.00

Third Parties:

Claimant:

Surveyor:

Workshop: Twincar Automotive Pte Ltd

ASSIGNMENT (Office)

From (Person): RAELENE of LAW Date/Time: 14/9/2021 5:27 PM

Estimated Cost: Bill to:

OD/TP Re-inspection / Evaluation

To Inspect Vehicle No: YM 6079U Insured: YP 8938L

at Workshop m/s Twincar Automotive Pte Ltd Tel: 6744 0510

of 2 KAKI BUKIT AVE 2 #01-17 KAKI BUKIT AUTOHUB SINGAPORE 417921

Policy No: CLE-atv-INS-T140-110802-19/SN Claim No: EQI.20.0320-WT/rs

Sum Insured: Excess:

Make of Veh: D.O.A. 03/12/2018

(Client's Record)

H.O.D. Endorsement/Date:

Date/Time: Person Contacted: Vehicle **IN / OUT**

Date/Time: Confirmed with Final Fig , days (Red $ / %; Original 14 days)

Date/Time: Submit Final Fig , days (Red $ / %; Original days)

Date/Time	Action/Instruction
	YM 6079U-NA/EQI18021810/h4 DOA : 03/12/2018
	YP 8938L - NA/EQI18021810/h4 DOA : 03/12/2018

Para(1) : Parts found not replaced (To highlight *R or UB, LR, Etc*)

Para(2) : Comments on consistency of damages (Parts Not Consistent : *NC*)

Para(3) : Nett Value

Market Value :

Salvage Value :

Nett Value :

Inspected/ Evaluated by:

Fee Charged:	*Date:*
Basic & Add	
Transport	
Photos	
Others	
Total	

1) Date/Time File Pass to 2) Date/Time File Return to

3) Date/Time File Pass to 4) Date/Time File Return to

5) Date/Time File Pass to 6) Date/Time File Return to