LKK Auto
the Repairer
- To resurvey before any spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

T K MOTOR WORKSHOP
1 KAKI BUKIT AVE 6 #02-56
SINGAPORE 417883
TEL : 96273323 FAX 68442641
CO.REG NO: 53049097-L

TP China.
Vecon.

ANANDA GANESH S/O SIVANANDAM

BLK 147 , LORONG 2 ,TOA PAYOH , #04-342

SINGAPORE 310147

DATE : 25/10/2021

WBAXG120S0DX51128

ACCIDENT DATE : 08/09/2021

ESTIMATE COST OF REPAIR BILL TO BMW 520I AUTO CAR NO : SFG989P

1 PC REAR L/H FENDER	Repair	S$1,850.00	X
1 PC REAR SPORT RIM L/H	cut	~~950.00~~	~~800~~(SN)
1 PC REAR L/H LOWER ARM		497.00	X
1 PC REAR L/H KNUCKLE ARM	New	699.00	X
1 PC REAR L/H KNUCKLE HUP & BEARING		527.00	X 1695
1 PC REAR L/H SHOCK ASBORBER		620.00	X. 1525.50
1 PC REAR BUMPER	torn	~~1,627.00~~	1563 S.N: 800
1 PC REAR BUMPER L/H SIDE RETAINER	cracked	96.00	✓
8 PC REAR BUMPER CLIPS	new	36.00	✓

LABOUR CHARGE

WIRING	~~50.00~~	30
COMPUTER WHEEL ALIGHTMENT	~~90.00~~	80
TO REMOVE & REFIX REAR UNDERCARRIAGE	280.00	X
TO REMOVE & REFIX REAR INTERIOR UPHOSLY	80.00	X 850
TO SPRAY PAINTING	~~450.00~~	400
TO APPLY UNDERCOATING ON THE REPAIRED PANEL	~~60.00~~	40
LABOUR CHARGE FOR PANEL BEATING & WELDING , REMOVING ALL DAMAGE PARS AND REPLACING OF THE NEW PARTS ETC.	~~380.00~~	300.

TOTAL : S$8,292.00

total: 2975.50
L/S: 2350.
04 Days