# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PRE-REPAIR INSPECTION REPORT

AXA INSURANCE PTE LTD	Ref:	CS3/ASM21009735/Bqce2
8 SHENTON WAY #24-01 AXA TOWER SINGAPORE 068811	Date:	06/10/2021
ATTN: TEO KITTY	Code:	ASM

1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	SHA 7895M	Veh. Inspected	SDV 4007S
Policy No.	VFX/P2419138	Coverage ($)	0.00
Claim No.	S1M03H4N	Excess ($)	0.00
Assign From	TEO KITTY	Assign Date	17/09/2021

2. Vehicle Particulars & Condition

Make & Model	VOLVO XC60 T5	c.c	1969
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	YV1DZ40LDF2661858	Colour	BLACK
Odometer	103004 KM	Steering	JAMMED
Brakes	IN ORDER	Modification	SPORTS RIM
General	POOR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	235/60 R18	GOODYEAR	5 mm
L/H Front Tyre	235/60 R18	GOODYEAR	5 mm
R/H Rear Tyre	235/60 R18	GOODYEAR	5 mm
L/H Rear Tyre	235/60 R18	GOODYEAR	5 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION.

5. General Information

Accident Date	01/09/2021	Inspect Date / Time	17/09/2021 (12:36 PM)
Survey held at	160 Sin Ming Drive #05-17 Sin Ming Autocity		
Repairer	HIAP LEK AUTOMOBILE TRADING		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.
D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF $15,000-$16,000

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **8 Working Days**

Report Ref No. CS3/ASM21009735/Bqce2

Inspected By

LIM TEOW GUAN

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser