

BIFROST AUTO PTE LTD

REPAIR ESTIMATE

DATE: 16-Sep-21

INSURANCE:

MODEL: HYUNDAI I40

VEHICLE NO.: SH 8330C

DESCRIPTION	QTY	LIST PRICE	AMOUNT
REAR DOOR (LH/RH) <i>Deutch</i>	1	\$ 2,201.10	\$2,201.10
REAR DOOR RUBBER (LH/RH) <i>HH</i>	1	\$ 280.50	\$280.50
REAR DOOR HINGE UPPER (LH/RH) <i>HH</i>	1	\$ 114.50	\$114.50
REAR DOOR HINGE LOWER (LH/RH) <i>HH</i>	1	\$ 123.50	\$123.50
REAR DOOR CHECK (LH/RH) <i>HH</i>	1	\$ 92.90	\$92.90
REAR DOOR TRIM BOARD (LH/RH) <i>HH</i>	1	\$ 808.70	\$808.70
ROCKER PANEL OUTER GARNISH (LH/RH) <i>int (defunct)</i>	1	\$ 732.80	\$732.80
FRONT FENDER (LH/RH) <i>Deutch</i>	1	\$ 663.00	\$663.00
FRONT FENDER SHIELD (LH/RH) <i>2.5V</i>	1	\$ 174.90	\$174.90
FRONT DOOR MIRROR ASSY (LH/RH) <i>HH</i>	1	\$ 893.50	\$893.50
FRONT DOOR (LH/RH) <i>Deutch</i>	1	\$ 2,256.40	\$2,256.40
FRONT DOOR RUBBER <i>SV</i>	1	\$ 290.50	\$290.50
FRONT DOOR GEAR/REGULATOR (LH/RH) <i>2.5V</i>	1	\$ 776.80	\$776.80
FRONT DOOR POWER MOTOR (LH) <i>HH</i>	1	\$ 172.70	\$172.70
FRONT DOOR TRIM BOARD (LH/RH) <i>HH</i>	1	\$ 997.40	\$997.40
DOOR CENTRE PILLAR OUTER (LH/RH) <i>Deutch</i>	1	\$ 2,527.80	\$2,527.80
FRONT WHEEL RIM (LH/RH) <i>diston</i>	1	\$ 650.60	\$650.60
FRONT WHEEL HUB CAP (LH/RH) <i>HF</i>	1	\$ 214.20	\$214.20
KNUCKLE ARM (LH/RH) <i>2.5V</i>	1	\$ 1,104.00	\$1,104.00
FRONT WHEEL BEARING AND HUB (LH/RH) <i>2.5V</i>	1	\$ 863.80	\$863.80
FRONT SUSPENSION LOWER ARM (LH/RH) <i>2.5V</i>	1	\$ 595.90	\$595.90
FRONT SHOCK ABSORBER ASSY (LH/RH) <i>2.5V</i>	1	\$ 684.40	\$684.40
STG TIE ROD (LH/RH) <i>HH</i>	1	\$ 186.40	\$186.40
STG TIE END (LH/RH) <i>HH</i>	1	\$ 125.20	\$125.20
STABILIZER BAR ASSY <i>HH</i>	1	\$ 463.70	\$463.70
STABILIZER BAR LINK (LH/RH) <i>HH</i>	1	\$ 85.90	\$85.90
FRONT WINDSCREEN GLASS <i>HH</i>	1	\$ 1,017.80	\$1,017.80
FRONT WINDSCREEN MOULDING <i>HH</i>	1	\$ 133.70	\$133.70
SUB TOTAL			\$19,232.60
LESS 20%			\$3,846.52
DISCOUNTED TOTAL			\$15,386.08
REAR DOOR TEL NO. STICKER (LH/RH) <i>HH</i> <i>HF</i> SN	1	\$ 10.00	\$10.00
Rear Door Comfortdelgro & Apps Sticker(LH/RH) <i>HH</i> SN	1	\$ 80.00	\$ 80.00
FRONT DOOR COMFORT LOGO (LH/RH) <i>HH</i> SN	1	\$ 75.00	\$75.00
FRONT TYRE (LH/RH) <i>HH</i> SN	1	\$ 216.00	\$216.00
FRONT WINDSCREEN SEALANT <i>HH</i> SN	1	\$ 46.00	\$46.00
FRONT ERP STICKER <i>HH</i> SN	1	\$ 26.00	\$26.00
SUB TOTAL			\$453.00
Labour Charge			

[illegible]

Panel Beating	1	\$ 1,800.00	\$1,800.00
Spray Painting Charge	1	\$ 1,600.00	\$1,600.00
Wiring Charge	1	\$ 100.00	\$100.00
Tuff Kote	1	\$ 100.00	\$100.00
Towing Charge	1	\$ 80.00	\$80.00
Transfer of Door Mechanism FRONT	1	\$ 80.00	\$80.00
Re-set Frt Power Window System	1	\$ 200.00	\$200.00
Transfer of Door Mechanism REAR	1	\$ 80.00	\$80.00
Re-set Rear Power Window System	1	\$ 200.00	\$200.00
Four Wheel Alignment	1	\$ 120.00	\$120.00
Remove/Refix Undercarriage (Frt)	1	\$ 400.00	\$400.00
Re-set Frt ABS System	1	\$ 200.00	\$200.00
Remove/Refix Front Windscreen Glass	1	\$ 120.00	\$120.00
Diagnostic & Resetting To Erase Fault Code	1	\$ 550.00	\$550.00
TOTAL LABOUR			\$5,630.00
ESTIMATE TOTAL			\$ 21,469.08

800/-
800/-
44
40/-
44
60/-
44
60/-
44
60/-
120/-
44
44
44

1970.00

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance

21/09/2021 09:15h

NA Actual

2/Some 7 days.

ryan

LKK Auto

8

11091.80

4/5 8800/-

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer.

Signature:

Date: