ASS. REC. BY: Sten | CC4 | GRB 210920 | G53

ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

at

Insured:

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

SIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Sum Sum: % 3 Vol.: Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted: Vehicle: IN / OUT

Veh No: SMU 837P Yr Regn: 31/8/20

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: Land Rover Discovery c.c 1997

Colour: Blue A/C: Insured / Std / NI / N

Sp.Reading: 12043 T/Radio: Insured / Std / NI / N

Eng/No:

C/No: SALCAIAXIEA 870798

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Locked / Burnt or

Brake: Inorder / Jammed / Locked / Burnt or

Mod: Nil / SIRim / STD A/Rim or

Tyre Size: F: 235/55R19

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or Pirelli

Front			Rear		
R/Bal.	4	mm	R/Bal.	4	mm
L/Bal.	4	mm	L/Bal.	4	mm
D.O.A.	25/9/21		D.O.I.	25/10/21	

Survey held at Wearnes

Des. of Damages: Fr. / Rear / O/S / N/S / U/C / Rooftop or Rear RH

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time	Action / Instruction
	MV - 280K

Date/Time, File Reopen: ☐ : Prell. Report ☐ : Final Report

Date/Time, File Returned

Days Of Repair:

Resurvey No. of Trip:

Add Fee: ☐ : Site Insp ($) ☐ : Interview ($) ☐ : Tech. Inve ($) ☐ : Weighbrid ($)

Survey Fee	
Transportation:	
Kms. $	
Parking	
Others	
TOTAL	