

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
 GST:201001158E RCB NO:201001158E

GBB5249H
 TP/AIG

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY
 #07-16 AIG BUILDING
 SINGAPORE 079120

TEL: 64193000

FAX: 64153727

ATTN: Motor Claim Department

Estimate No: ES2190921/YISHUN

Date: 29 Sep 2021

Policy No: Z/21/VC00/110925

Veh Reg No: GBB5249H

Make/Model: FIAT FIORINO 1.3MJTD
 (225.2L20)

WS Ref: TP/AIG

Claim Type: Third Party

Accident Date: 28/09/2021

TP Veh Reg No: GBL1338H

Chassis No: ZFA22500000059447

Engine No: 199A20003053439

Reg. Date: 27/05/2009

Estimate Repair Cost to Vehicle No :GBB5249H

Description	U/Price	Quantity	List Price	Amount
			S\$	S\$
List Price				
1 REAR BUMPER	750.00	1 PC	750.00	✓
2 REAR BUMPER REINFORCEMENT	480.00	1 PC	480.00	✓
3 LH TAILGATE	1,680.00	1 PC	1,680.00	✓
4 TAILGATE EMBLEM (FIORINO)	60.00	1 PC	60.00	✓
5 TAILGATE OUTER HANDLE	90.00	1 PC	90.00	✓
6 TAILGATE INNER LOCK	340.00	1 PC	340.00	✓
7 TAILGATE INNER BOARD	185.00	1 PC	185.00	✓
8 TAILGATE GLASS LH	470.00	1 PC	470.00	✓
9 TAILGATE GLASS INNER LOCK LH	380.00	1 PC	380.00	✓
10 TAILGATE GLASS INNER BOARD LH	190.00	1 PC	190.00	✓
11 TAILGATE INNER RUBBER LH	190.00	1 PC	190.00	✓
12 REAR WIPER ARM	125.00	1 PC	125.00	✓
13 REAR WIPER ARM CAP	25.00	1 PC	25.00	✓
14 TAILLAMP LH	385.00	1 PC	385.00	✓
15 RH TAILGATE	1,750.00	1 PC	1,750.00	✓
16 RH TAILGATE LOGO	130.00	1 PC	130.00	✓
17 RH TAILGATE EMBLEM (MULTIJET)	50.00	1 PC	50.00	✓
18 RH TAILGATE GLASS	490.00	1 PC	490.00	✓
19 RH TAILGATE INNER LOCK	370.00	1 PC	370.00	✓
20 RH TAILGATE INNER RUBBER	210.00	1 PC	210.00	✓
21 RH TAILGATE INNER BOARD	120.00	1 PC	120.00	✓
22 REAR END PANEL OUTER	400.00	1 PC	400.00	✓
			8,870.00	
		Less 10%	887.00	7,983.00
Special Net				
23 LH TAILGATE GLASS GUM	30.00	1 PC	30.00	✓
24 RH TAILGATE GLASS GUM	30.00	1 PC	30.00	✓
25 STICKER - 70KM/H	10.00	1 PC	10.00	✓
26 STICKER - 3 PAX	10.00	1 PC	10.00	✓
27 REVERSE SENSOR	200.00	1 SET	200.00	✓
			280.00	280.00
Labour				
28 REMOVE & REFIX LEFT & RIGHT TAILGATE GLASS	160.00	1 LA	160.00	140

Not Notched
 1/1 Png 87700h
 Presumy After Pging
 7 days

Shattered

Reverse

Shattered

50% 95%

50% 105%

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120
TEL: 64193000 FAX: 64153727
ATTN: Motor Claim Department

WS Ref: TP/AIG
Claim Type: Third Party
Accident Date: 28/09/2021
TP Veh Reg No: GBL1338H

Estimate No: ES2190921/YISHUN
Date: 29 Sep 2021
Policy No: Z/21/VC00/110925
Veh Reg No: GBB5249H
Make/Model: FIAT FIORINO 1.3MJTD
(225.2L20)
Chassis No: ZFA22500000059447
Engine No: 199A20003053439
Reg. Date: 27/05/2009

Estimate Repair Cost to Vehicle No :GBB5249H

Description	U/Price	Quantity	List Price	Amount
			<u>S\$</u>	<u>S\$</u>
29 REMOVE & REFIX TAILGATES,REAR BUMPER ASSY,REAR LOCK ASSY,REAR WIPER,CUT,WELD & RENEW REAR END PANEL OUTER,KNOCK & REPAIR REAR END FLOOR BOARD PANEL,LH SIDE PANEL CORNAL & REALIGN THE SAME	1,000.00	1 LA	1,000.00	800
30 REMOVE & REFIX REAR GARNISH, TOP ROOF LINING,CARPET,ETC	120.00	1 LA	120.00	100
31 PUTTY & RESPRAY ON REAR LH SIDE PANEL,REAR FLOOR BOARD PANEL,REAR END PANEL,TAILGATES	1,000.00	1 LA	1,000.00	900
32 RUSTPROOFING	90.00	1 LA	90.00	✓
			2,370.00	2,370.00
			Total	S\$ 10,633.00
			Add GST @ 7%	744.31
			Total Amount Payable	S\$ 11,377.31

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE