Vfix Auto Pte Ltd
26 Chin Ping Road
Singapore 419977
Email: contact@vfixauto.com.sg
Tel: 64552957 Fax: 68426669
UEN / GST REG No : 201830761R

ESTIMATE

DATE 29/9/2021

SHEET NO. 1 OF 1 SHEET

Attention: Motor Claim Department

RE : VEHICLE NO : XD9336S (PENG CHUAN ENGINEERING CONSTRUCTION PTE LTD)

S/NO.	QTY	DESCRIPTION	UNIT S$	AMOUNT S$	
1	2	REAR MUDGUARD	450 ~~1,500.00~~	3,000.00	950
2	6	REAR MUDGUARD BRACKET	150.00	900.00	120
3	2	REAR MUDFLAP	200 ~~250.00~~	500.00	200
4	1	REAR CENTER PANEL		2,650.00	1000
5	2	TAILLAMP	200.00	400.00	200
6	2	TAILLAMP PANEL	120 ~~150.00~~	300.00	120
7	1	TAILGATE RUBBER		350.00	X
				$ 8,100.00	
		LESS 10%		$ 7,290.00	2590 -10% 2331

S/NO.	QTY	DESCRIPTION	UNIT PRICE	AMOUNT S$	
		SPECIAL NET			
1	1	BODY SEALANT		$ 60.00	30
2	1	REAR NUMBER PLATE		$ 25.00	20
3	1	REAR NUMBER PLATE HOLDER		$ 25.00	20
				$ 60.00	70

S/NO.	QTY	LABOUR & MISCELLANEOUS :	AMOUNT S$	
1	1	To remove damaged body panel with all necessary components/attachments apply hot-works where necessary straighten front door pillar,repair/reshape body dented panels in accordance with factory specifications replace new parts refit and align into position refit all necessary components / attachments	$ 1,500.00	500
1	1	To spray paint replaced/repaired body panels inclusive of preparatory works and painting materials	$ 1,000.00	400
1	1	Towing Fees	$ 120.00	X
1	1	To check, reconncect, repairing all the wiring	$ 120.00	30
			$ 2,740.00	
		GRAND TOTAL :	**$ 10,090.00**	930

ISSUED BY

weng sheng

KOH WENG SHENG

Steve (LKK)
29/9/21

ESTIMATE CONFIRMED AND ACCEPTED BY

[redacted]

NAME, SIGNATURE, DATE SIGNED

[redacted]

hL AL
L/S
Ny AL Sy
4 L/S

Please notify
towing:
parking
survey
"prejudice" basis
Company
Authorised by Repairer

Scanned with CamScanner