SURVEYED BY: Thevan | ... china

ASSIGNMENT

From: Date.

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rport: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs. 3 days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SHA[illegible]9092A ✓ Yr Rogn: 13/2 ,20

Type: M.Car / M.Cycle / Bus / Van / Lorry / (Taxi) / Prime Mover / Truck / Trailer or

Make: Hyundai Ioniq c.c 1580

Colour: yellow A/C: . Insured / Std / NI / NA

Sp.Reading 101498 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: KMHC851CULU184244

Gen. Cond: (Good) / Fair / Poor / Burnt

Steering: (In order) / Jammed / Leaked / Burnt or

Brake: (In order) / Jammed / Leaked / Burnt or

Modi: Nil / (S/Rim) / STD A/Rim or

Tyre Size: F: 195/65R15

R: 195/65R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or Westlake

Front			Rear		
R/Bal.	5	mm	R/Bal.	5	mm
L/Bal.	5	mm	L/Bal.	5	mm

D.O.A. 20/9/21 D.O.I. 21/9/21 1645

Survey held at Comfort

Des. of Damages: Frt / Rear / (O/S) / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	NO GIA given

Date/Time File Pass to? [ ] : Prell. Report

[ ] : Final Report

Date/Time File Return to?

Report Format:

Days Of Repair:

Resurvey No. of Trip:

Add Fee: [ ] : Site Insp ($)
[ ] : Interview ($)
[ ] : Tech. Inve ($)
[ ] : Weekend ($)

Survey Fee:	
Transportation:	
__S + RS. __SI	
Photos	
Others	
TOTAL	

REPAIR ESTIMATE*

VEHICLE NO **SHA9092A** **DATE 20/09/2021**

MAKE **13.02.2020**

MODEL **: HYUNDAI IONIQ G3** **CHIANG /CHINA**

Qty	Parts Description/ Labour	Type	Unit Price	Amount
1	FRONT BUMPER COVER			$430.90 / Cut
1	FRONT BUMPER CENTRE MOULDING			$368.50 X SVC
1	FRONT BUMPER GRILLE RH			$93.45 X SVC
1	FRT RH DAY LIGHT			$642.50 X SVC
1	FRONT FENDER RH			$588.80 / Def
1	FRONT FENDER SHIELD			$164.70 X SVC
1	FRONT BRACKET SIDE RH			$35.00 / NLC
1	FRONT FENDER EMBLEM RH			$26.60 / NLC
1	HEAD LAMP RH			$1,993.65 X SVC
1	FRONT WHEEL CAP RH			$346.40 / SCr
10	BUMPER CLIP			$22.00 / NLC
				$4,712.50
	20.00%			$942.50
	DISCOUNTED TOTAL			**$3,770.00**
	Labour Charge			
	Panel Beating			$700.00 /
	Spray Paint			$600.00 500
	Reset Front Wheel Alignment			$60.00 /
	Check lighting			$60.00 30
	TOTAL LABOUR			**$1,420.00**
	ESTIMATE TOTAL			**$5,190.00**

Thevan@lkkauto.com
82235769
P/P ~~after~~ b4 for paint photos
21/9/21 1645
3 days WP

LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.