

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
 GST:201001158E RCB NO:201001158E

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
 78 SHENTON WAY
 #07-16 AIG BUILDING
 SINGAPORE 079120

TEL: 64193000
 ATTN: Motor Claim Department

FAX: 64153727

WS Ref: TP/AIG/AMK
 Claim Type: Third Party
 Accident Date: 11/10/2021
 TP Veh Reg No: GBF6472B

Estimate No: ES2190971/AMK

Date: 12 Oct 2021

Policy No: 5101357523-03

Veh Reg No: SLU7850P

Make/Model: TOYOTA COROLLA
 ALTIS 1.6 AUTO

Chassis No: MR053REH604575869

Engine No: 1ZR0A39782

Reg. Date: 14/12/2017

Not Notarised
1/1/2021
Recovery After Repair

Estimate Repair Cost to Vehicle No :SLU7850P

Description	U/Price	Quantity	List Price	Amount
			S\$	S\$
List Price				
1 FRONT BUMPER	531.10	1 PC	Bu 531.10	✓
2 FRONT BUMPER REINFORCEMENT	399.50	1 PC	R 399.50	X
3 FRONT BUMPER SPONGE	111.80	1 PC	CM 111.80	✓
4 FRONT BUMPER SIDE RETAINER	68.20	2 PC	Di 136.40	✓
5 FRONT BUMPER CLIP	4.50	6 PC	Me 27.00	✓
6 FRONT BUMPER CENTRE LOWER GRILLE	169.60	1 PC	CM 169.60	✓
7 FRONT GRILLE ASSY	712.10	1 PC	CM 712.10	✓
8 FRONT GRILLE UPPER GARNISH	80.70	1 PC	Di 80.70	✓
9 FRONT GRILLE CLIP	4.50	4 PC	Me 18.00	✓
10 BONNET <i>1248.80</i>	1,248.80	1 PC	R 1,248.80	✓
11 BONNET INNER LOCK	135.00	1 PC	R 135.00	✓
12 BONNET HINGE	58.90	2 PC	Di 117.80	✓
13 BONNET INSULATOR <i>Return</i>	280.10	1 PC	280.10	✓
14 BONNET CLIP	3.70	6 PC	Me 22.20	✓
15 HEADLAMP <i>T81070/181140-02N30 m3 CM</i>	3,970.80	2 PC	7,941.60	✓
16 HEADLAMP CHROME	144.60	2 PC	Me 289.20	✓
17 FRT SUPPORT PANEL ASSY <i>1136.30</i>	1,136.30	1 PC	R 1,136.30	✓
18 FRT BRACE PANEL	164.90	1 PC	R 164.90	✓
19 AIR-CON CONDENSER <i>1801.70</i>	1,801.70	1 PC	R 1,801.70	✓
20 RADIATOR <i>2148.90</i>	2,148.90	1 PC	R 2,148.90	✓
21 RADIATOR TOP COWLING	101.00	1 PC	CM 101.00	✓
22 RADIATOR FAN COWLING	297.20	1 PC	Sm 297.20	X
23 RADIATOR FAN MOTOR	535.50	1 PC	Sm 535.50	X
24 RADIATOR FAN BLADE	180.40	1 PC	Sm 180.40	X
25 RADIATOR TOP BRACKET	59.70	2 PC	Di 119.40	✓
26 ENGINE INTAKE MANIFOLD	898.30	1 PC	Sm 898.30	X
			19,604.50	
Less 25%			4,901.13	14,703.38
Special Net				
27 FRONT NUMBER PLATE	35.00	1 PC	R 35.00	✓
28 COOLANT	35.00	1 UNIT	Me 35.00	✓
			70.00	70.00
Labour				
29 REMOVE AND REFIX AIRCON,CHECK,VACUUM & REFILL GAS	100.00	1 LA	100.00	✓

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

M/S: AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120

TEL: 64193000

FAX: 64153727

ATTN: Motor Claim Department

WS Ref: TP/AIG/AMK

Claim Type: Third Party

Accident Date: 11/10/2021

TP Veh Reg No: GBF6472B

Estimate No: ES2190971/AMK

Date: 12 Oct 2021

Policy No: 5101357523-03

Veh Reg No: SLU7850P

Make/Model: TOYOTA COROLLA
ALTIS 1.6 AUTO

Chassis No: MR053REH604575869

Engine No: 1ZR0A39782

Reg. Date: 14/12/2017

Estimate Repair Cost to Vehicle No :SLU7850P

Description	U/Price	Quantity	List Price	Amount
30 REMOVE & REFIX FRT BUMPER & ATTACHMENTS,BONNET & ATTACHMENTS,GRILLE, HEADLAMPS;TO CUT,WELD & RENEW FRT PANEL;KNOCKING & REPAIR FRT FENDERS & REALIGN THE SAME	900.00	1 LA	900.00	700
31 PUTTY & RESPRAY FRT BUMPER,BONNET,BOTH FENDERS,FRT PANEL & ALL AFFECTED AREAS	900.00	1 LA	900.00	800
32 REMOVE & REFIX ENGINE INTAKE MANIFOLD & REALIGN THE SAME	120.00	1 LA	120.00	X
33 RUSTPROOFING	60.00	1 LA	60.00	✓
			2,080.00	2,080.00
Total				S\$ 16,853.38
Add GST @ 7%				1,179.74
Total Amount Payable				S\$ 18,033.12

* SURVEY VEHICLE AT ANG MO KIO WORKSHOP

For Cheng Hoe Motor Pte Ltd

Dorlyn

AUTHORISED SIGNATURE

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: