ASS. Filed By: GQ | REF: CS/MSG21010508/Gvf3

ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s SBS

of

Insured: GBK 7335G

Policy No. 1001545417

Claims No. 263898

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rport: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 2 days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SBS6009M Yr Regn: 27 May 2011

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: MERCEDES BENZ CITARO O530c.c 6374

Colour Multicolor A/C: Insured / Std / NI / NA

Sp.Reading 632876.9 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: WEB62808323121903 *

Gen. Cond Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi : Nil / S/Rim / STD A/Rim or

Tyre Size: F: 275/70R22.5

R: 275/70R22.5

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front		Rear	
R/Bal.	6 mm	R/Bal.	6/6 mm
L/Bal.	6 mm	L/Bal.	6/6 mm

D.O.A. 11/10/21 D.O.I. 13-10-2021

Survey held at W/S 11AM

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or O/S REAR

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	NO GIA PROVIDED, ESTIMATE WILL EMAIL LATER
20/10/21	Submit $2427.80 (un-confirmed) (Red 0)

Date/Time, File Pass to? 1)

Date/Time, File Return to? 2) 20/10/21-typist

☐ : Preli. Report

☐ : Final Report

Days Of Repair: 2

Resurvey No. of Trip: 2

Add Fee: ☐ : Site Insp ($)

☐ : Interview ($)

☐ : Tech. Invs ($)

☐ : Weekend ($)

Report Format : Merimen

Lump Sum / UPD :

Survey Fee:

Transportation: S + RS. SI

Photos

Other:

TOTAL